



# OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office  
Ohio Historical Center  
Columbus, Ohio 43211

<p>1. No. <b>158 FRA-1856-70</b></p> <p>2. County <b>FRANKLIN</b></p> <p>3. Location of Negatives <b>OHS</b></p>	<p>4. Present Name(s) <b>MAPLE GROVE UNITED METHODIST CHURCH</b></p> <p>5. Other Name(s)</p>	<p style="writing-mode: vertical-rl; transform: rotate(180deg);">1. No. <b>158</b></p> <p style="writing-mode: vertical-rl; transform: rotate(180deg);">2. County <b>FRANKLIN</b></p> <p style="writing-mode: vertical-rl; transform: rotate(180deg);">4. Present Name(s) <b>MAPLE GROVE UNITED METHODIST CHURCH</b></p> <p style="writing-mode: vertical-rl; transform: rotate(180deg);">5. Other Name(s)</p>
<p>6. Specific Location <b>7 W. HENDERSON RD.</b></p>	<p>16. Thematic Category <b>D 20TH CEN. ARCH.</b></p> <p>17. Date(s) or Period <b>CORNERSTONE 1941</b></p> <p>18. Style or Design</p> <p>19. Architect or Engineer <b>RALPH ORR</b></p> <p>20. Contractor or Builder</p> <p>21. Original Use, if apparent <b>CHURCH</b></p> <p>22. Present Use <b>CHURCH</b></p> <p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name &amp; Address, if known <b>MAPLE GROVE UNITED METHODIST 7 W. HENDERSON. COS. O.</b></p> <p>25. Open to Public? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>26. Local Contact Person or Organization <b>NEWTON A. FRITCHLEY.</b></p> <p>27. Other Surveys in Which Included</p>	<p>28. No. of Stories <b>1</b></p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material <b>STONE</b></p> <p>31. Wall Construction <b>STONE</b></p> <p>32. Roof Type &amp; Material <b>GABLED / SHINGLE</b></p> <p>33. No. of Bays Front <b>8</b> Side <b>C</b></p> <p>34. Wall Treatment <b>ROUGH STONE</b></p> <p>35. Plan Shape <b>IRREG.</b></p> <p>36. Changes (Explain in #42) Addition <input checked="" type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior <b>GOOD</b> Exterior <b>GOOD</b></p> <p>38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road <b>35' x 100'</b></p>
<p>7. City or Town If Rural, Township &amp; Vicinity <b>COLUMBUS</b></p> <p>8. Site Plan with North Arrow</p>  <p>9. Coordinates Lat. _____ Long. _____ U.T.M. Reference Zone _____ Easting _____ Northing _____</p> <p>10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/></p> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>15. Name of Established District</p>	<p>42. Further Description of Important Features <b>CHURCH IS CONSTRUCTED OF LIMESTONE. LIMESTONE IS CUT IN IRREGULAR ROUGH BLOCKS. WINDOWS ARE LEADED STAINED GLASS. THERE IS A ROUND WINDOW ON THE N. END OF THE CHURCH. THE CHURCH IS BUTTRESSED AT THE CORNERS. THERE IS AN EDUCATIONAL UNIT ON THE S.W. SIDE WHICH IS CONSTRUCTED OF BRICK. THE CHAPEL'S CEILING AND MAIN SANCTUARY CEILING ARE CATHEDRAL TYPE WITH OAK BEAMS.</b></p>	
<p>43. History and Significance <b>CHURCH WAS BUILT IN SECTIONS FIRST SECTION BUILT IN 1941, SECOND SECTION IN 1954. CHURCH WAS FOUNDED IN 1919</b></p>	<p>44. Description of Environment and Outbuildings <b>LOCATED A MAJOR INTERSECTION. SURROUNDING AREA IS COMMERCIAL ALONG HIGH STREET AND RESIDENTIAL ON HENDERSON.</b></p>	
<p>45. Sources of Information <b>VISUAL INSPECTION. CORNER STONE CHURCH PERSONNEL.</b></p>	<p>46. Prepared by <b>HOBBSTETTER</b></p> <p>47. Organization <b>COS. INV.</b></p> <p>48. Date <b>8-27-25</b></p> <p>49. Revision Date(s)</p>	

51. Condition of Property

- |                                       |   |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent    | <input type="checkbox"/> Ruin             |
| <input type="checkbox"/> Good/Fair    | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____                                |

52. Historic Outbuildings and Dependencies

Barn Type(s)

---



---

- |  |                                       |                                 |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/>           | Smoke House <input type="checkbox"/>  | Privy <input type="checkbox"/>  |
| Summer Kitchen <input type="checkbox"/>              | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/>                        | Ice House <input type="checkbox"/>    |                                 |
| Designed landscape features <input type="checkbox"/> |                                       |                                 |

53. Affiliated OAI Site Number(s) \_\_\_\_\_ one \_\_\_\_\_ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	└
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
└	.	.	.	┌

42. (Cont'd)

43. (Cont'd)