1985 Velma Avenue Columbus, Ohio 43211



OHIO HISTORIC	INVENTORY 1985 Velma Avenue Columbus, Ohio 432 614/297-2470	
1. No. FRA-5351-70 2. County Franklin 3. Location of Negatives	4. Present Name(s)	Coded Coded
Roll No. Picture No.(s)	5. Historic or Other Name(s)	3.57_10
6. Specific Address or Location 629A Oakland Park	16. Thematic Association(s) Residential - Commerce 17. Date(s) or Period 17b. Alteration Date(s)	28. No. of Stories 29. Basement? Yes X 7 0 unity No D 1.5
6a. Lot, Section or VMD Number 7. City or Village If Rural, Township & Columbus	Vicinity 18. Style or Design Wernacular 18a. Style of Addition or Element(s) High Style Elements	30. Foundation Material Rough face conc. blk. 31. Wall Construction Wood frame
8. Site Plan with North Arrow	19. Architect or Engineer	32. Roof Type & Material Cross Gable/Slate 33. No. of Bays
Oakland Park Ave.	19a. Design Sources 20. Contractor or Builder	Front 3 Side 2 34. Exterior Wall Material(s) Asbestos shingle
N1	21. Building Type or Plan	Front 3 Side 2 34. Exterior Wall Material(s) Asbestos shingle 35. Plan Shape Irregular 36. Changes Addition X (Explain Altered X in #42) Moved 37. Window Type(s)
9. U.T.M. Reference Quadrangle Name Northeast Columbination 1 7 3 2 9 4 8 0 4 4 3 3 0 Zone Easting Northing 10. Site Structure	Commercial 24. Ownership Public Private X	☐ 6 over 6 ☐ 2 over 2 ☐ 4 over 4 ☐ 2 Other 1/1 38. Building Dimensions 8 x 15m 39. Endangered? Yes ☐
11. On National Yes 12. N.R. Yes Register? No 2 Potential? N. 13. Part of Estab. Yes 14. District Yes	25. Owner's Name & Address, if known 25. Owner's Name & Address, if known 26. Property Acreage 27. Other Surveys in Which Included	By What? 40. Chimney Placement Center ridge interior 41. Distance from and Frontage on Road
42. Further Description of Important Interior and E The front facade has a large block foundation and flat ro on the east side. The front window, cornice returns, and is interrupted by a cross gal dormer on the east facade of The east cross gable has cor window on the second floor. 43. History and Significance (Continue on reverse This structure is not indicate	6. Specific Address or Location 629A Oakland Park North west Elevations Elevations	
44. Description of Environment and Outbuildings In the middle of two commerc concrete block building in the	ASC, Inc. 47. Organization ASC, Inc.	
45. Sources of Information Field observation. Multi-mode	al Transportation Corridor Study, 1994	48. Date Recorded in Field 4-28-94 49. Revised by 50a. Date Revised 50b. Reviewed by SCG AU6 2 4 1994

51. Condition of Property		54. Farmstead Plan					
☐ Excellent	Ruin		F				$\overline{\cdot}$
☐ Good/Fair	☐ Destroyed/E	Burned	1				
☐ Deteriorated	Date						
52. Historic Outbuildings and Dependencies				•	•		
Barn Type(s)							
Barr Type(s)							
Corn Crib or Shed \square	Smoke House						
Summer Kitchen	Spring House				•		
Silo 🗆	Ice House						
Designed landscape features							
				•			
53. Affiliated OAI Site Number(s)	one	multiple					
Archaeological Feature:	Observed	Expected on Basis of					
Alonacological Feature.	00001100	Archival Research		•			
Well							
Privy							
Cistern							
Foundation		4					
Structural Rubble	· <u>/ · · · · · · · · · · · · · · · · · ·</u>						
Formal Trash Dump							
Other			Ŀ				
							1905-F-1807-W
42 (Cont'd)							

42. (Cont'd)

43. (Cont'd)