

OHIO HISTORIC INVENTORY

Historic Preservation Office
Ohio Historical Society
Columbus, Ohio 43211

1. No. H-001 FRA-90-3	4. Present Name(s) Residence of Mrs. R.W. Kissane
2. County Franklin	5. Other Name(s)
3. Location of Negatives Craig L. Mount	

6. Specific Location
4817 Olentangy Blvd.

7. City or Town If Rural, Township & Vicinity
Columbus, Ohio



9. Coordinates UTM
Lat. ~~40° 2'~~ **40° 3' 32"**
Long. **83° 1' 34"**

10. Site Building Structure Object

11. On National Register? Yes No 12. Is It Eligible? Yes No

13. Part of Estab. Hist. Dist.? Yes No 14. District Potent'l? Yes No

15. Name of Established District

16. Thematic Category
Architecture * 20'th Cent.

17. Date(s) or Period
Built 1935

18. Style or Design
acc. to architect: "New Orleans Georgian"

19. Architect or Engineer
ROBERT R. Reeves

20. Contractor or Builder
G. Atkinson

21. Original Use, if apparent
residence

22. Present Use
residence

23. Ownership Public Private

24. Owner's Name & Address, if known
**Mrs. R.W. Kissane
4817 Olentangy Blvd., Col.**

25. Open to Public? Yes No

26. Local Contact Person or Organization

27. Other Surveys in Which Included

28. No. of Stories **2**

29. Basement? Yes No

30. Foundation Material
concrete & conc. blo

31. Wall Construction
solid brick

32. Roof Type & Material
Medium hip - slate

33. No. of Bays Front **6** Side **3**

34. Wall Treatment
plastered & painted

35. Plan Shape

36. Changes (Explain in #42) Addition Altered Moved

37. Condition Interior **Excellent** Exterior **Excellent**

38. Preservation Underway? Yes No

39. Endangered? By What? Yes No

40. Visible from Public Road? Yes No

41. Distance from and Frontage on Road
dist. -100'; fron. -50'

42. Further Description of Important Features
Central fireplace allows significant areas of glass on the west wall of the living room, thus providing excellent views (from the ridge upon which the house is built) up & down the Olentangy River. This fireplace also serves an upstairs bedroom. The entryway is a pleasant & unique New Orleans accent. Kitchen was remodeled, but not extensively nor in disharmony with the rest of the house.



43. History and Significance
This is reportedly the last house or bldg. ever built by the late Mr. Reeves. In fact, according to Mrs. Kissane (who has lived in this home continuously since her husband and her commissioned its building), Mr. Reeves died the very night at Presutti's Restaurants after inspecting the plaster on the house.

44. Description of Environment and Outbuildings
There are no outbuildings on the property. The environment is very much residential and seemingly very quiet and tranquil. The property is comfortably wooded, as is the entire neighborhood. The river lies directly behind the house

45. Sources of Information **at the bottom of a steep grade.**

Mrs. R.W. Kissane
personal observation

46. Prepared by
CLIMOUNT

47. Organization
Arch 694 - O.S.U.

48. Date **11/25/74** 49. Revision Date(s) **1/2/75**

1. No. **H-001**
2. County **FRANKLIN**
4. Present Name(s) **RESIDENCE OF MRS R.W. KISSANE**
5. Other Name(s)

51. Condition of Property

- Excellent Ruin
 Good/Fair Destroyed/Burned
 Deteriorated Date _____

52. Historic Outbuildings and Dependencies

Barn Type(s)

- Corn Crib or Shed Smoke House Privy
 Summer Kitchen Spring House Garage
 Silo Ice House
 Designed landscape features

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	└
.
.
.
.
.
.
.
└	└

42. (Cont'd)

43. (Cont'd)