

# OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office  
Ohio Historical Center  
Columbus, Ohio 43211

ADNEA 10

1. No. FRA-1535-13  
2. County FRANKLIN  
3. Location of Negatives O.H.S.


4. Present Name(s) 96-98 EAST DODRIDGE  
5. Other Name(s)  
**CODED**

1. No. FRA-1535-13  
2. County FRANKLIN  
4. Present Name(s) 96-98 EAST DODRIDGE

6. Specific Location  
96-98 E DODRIDGE ST.  
NW CORNER W/ FINDLAY  
7. City or Town If Rural, Township & Vicinity  
COLUMBUS  
8. Site Plan with North Arrow

16. Thematic Category  
17. Date(s) or Period  
ca 1938  
18. Style or Design  
INTERNATIONAL STYL  
19. Architect or Engineer

28. No. of Stories 2  
29. Basement? Yes  No   
30. Foundation Material  
?  
31. Wall Construction  
BRICK  
32. Roof Type & Material  
FLAT ?



20. Contractor or Builder  
21. Original Use, if apparent  
RESIDENCE  
22. Present Use  
RESIDENCE

33. No. of Bays  
Front 4 Side 2  
34. Wall Treatment  
COMMON FLEMISH  
35. Plan Shape RECT

9. Coordinates  
Lat. \_\_\_\_\_ Long. \_\_\_\_\_  
U.T.M. Reference

23. Ownership Public  Private   
24. Owner's Name & Address, if known  
61593  
VIOLET M HAYDEN  
96 DODRIDGE ST  
COL

36. Changes Addition  Altered  Moved   
37. Condition Interior \_\_\_\_\_ Exterior GF FAIR

10. Site Building  Structure Object   
11. On National Register? Yes  No   
12. Is it Eligible? Yes  No   
13. Part of Estab. Hist. Dist.? Yes  No   
14. District Potent'l? Yes  No

25. Open to Public? Yes  No   
26. Local Contact Person or Organization  
27. Other Surveys in Which Included

38. Preservation Underway? Yes  No   
39. Endangered? By What? Yes  No   
40. Visible from Public Road? Yes  No   
41. Distance from and Frontage on Road  
45' y 45'

15. Name of Established District

42. Further Description of Important Features  
WRAP-AROUND CORNER WINDOWS  
TRIPLE BRICK BELT COURSE



5. Other Name(s)

43. History and Significance  
ONE OF THE FEW INTERNATIONAL STYLES HOUSES  
OBSERVED IN THE NORTH COLUMBUS AREA

44. Description of Environment and Outbuildings  
ARCADIA LOT 9-10 - ON A STREET WHICH  
HAS A UNIQUE VIEW OF OPEN FIELDS TO THE WEST ACROSS THE  
OLONTANGY VALLEY

45. Sources of Information  
COL. CITY DIRECTORY 1938

46. Prepared by  
CS  
47. Organization  
CI  
48. Date  
JAN 83  
49. Revision Date(s)

12

51. Condition of Property

- |                                       |   |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent    | <input type="checkbox"/> Ruin             |
| <input type="checkbox"/> Good/Fair    | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____                                |

52. Historic Outbuildings and Dependencies

Barn Type(s)

---



---

- |  |                                       |                                 |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/>           | Smoke House <input type="checkbox"/>  | Privy <input type="checkbox"/>  |
| Summer Kitchen <input type="checkbox"/>              | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/>                        | Ice House <input type="checkbox"/>    |                                 |
| Designed landscape features <input type="checkbox"/> |                                       |                                 |

53. Affiliated OAI Site Number(s) \_\_\_\_\_ one \_\_\_\_\_ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

<input type="checkbox"/>	.	.	.	<input type="checkbox"/>
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
<input type="checkbox"/>	.	.	.	<input type="checkbox"/>

42. (Cont'd)

43. (Cont'd)