


OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

<p>1. No. FRA-1655-13</p> <p>2. County FRANKLIN</p> <p>3. Location of Negatives OHS</p>	<p>4. Present Name(s) 45 E CRESTVIEW ROAD</p> <p style="text-align: right; font-size: 2em; opacity: 0.5;">CODED</p> <p>5. Other Name(s)</p>	
<p>6. Specific Location 45 CRESTVIEW RD 2 W of EAST AVE</p>	<p>16. Thematic Category D</p> <p>17. Date(s) or Period ca 1910-20</p> <p>18. Style or Design BUNGALOID</p> <p>19. Architect or Engineer</p> <p>20. Contractor or Builder</p> <p>21. Original Use, if apparent HOUSE</p> <p>22. Present Use HOUSE</p> <p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name & Address, if known LORETTA J DANIELS C-O STATE SAVINGS CO.</p> <p>25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>26. Local Contact Person or Organization</p> <p>27. Other Surveys in Which Included</p>	<p>28. No. of Stories 1 1/2</p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material STONE</p> <p>31. Wall Construction WOOD FRAME</p> <p>32. Roof Type & Material GABLE ASH SHINGLE</p> <p>33. No. of Bays Front 4 Side 4</p> <p>34. Wall Treatment WOOD SHINGLES</p> <p>35. Plan Shape RECT</p> <p>36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior _____ Exterior GOOD</p> <p>38. Preservation Underway? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road 40' x 60'</p>
<p>7. City or Town If Rural, Township & Vicinity COLUMBUS</p> <p>8. Site Plan with North Arrow </p>	<p>9. Coordinates Lat. _____ Long. _____ U.T.M. Reference Zone _____ Easting _____ Northing _____</p>	
<p>10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/></p> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>15. Name of Established District</p>	<p>42. Further Description of Important Features LARGE OVERHANGING EAVES w/ BRACKETS LOWER WALL BATTERED PLAIN FASCIA ON SIDES</p>	
<p>43. History and Significance</p>		
<p>44. Description of Environment and Outbuildings CRESTVIEW LOTS 696-699 - ALONG A STREET THAT WAS GENERALLY DEGENERATED AFTER WWI AND DURING THE 1920'S.</p>		
<p>45. Sources of Information PAST'S PROPERTY ATLAS 1910 " " " 1920</p>	<p>46. Prepared by CS</p> <p>47. Organization CI</p> <p>48. Date DAUG 75</p> <p>49. Revision Date(s)</p>	

1. No. **FRA-1655-13**
 2. County **FRANKLIN**
 3. Present Name(s) **45 E CRESTVIEW ROAD**
 4. Present Name(s) **45 E CRESTVIEW ROAD**
 5. Other Name(s)



51. Condition of Property

- | | |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Ruin |
| <input type="checkbox"/> Good/Fair | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____ |

52. Historic Outbuildings and Dependencies

Barn Type(s)

- | | | |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/> | Smoke House <input type="checkbox"/> | Privy <input type="checkbox"/> |
| Summer Kitchen <input type="checkbox"/> | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/> | Ice House <input type="checkbox"/> | |
| Designed landscape features <input type="checkbox"/> | | |

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌				┐

└				┘

42. (Cont'd)

43. (Cont'd)