


# OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office  
Ohio Historical Center  
Columbus, Ohio 43211

1. No. FPA-1663-183 4. Present Name(s) 334 WALHALLA ROAD  
 2. County FRANKLIN 5. Other Name(s)   
 3. Location of Negatives OHS

CODED

1. No. FPA-1663-183  
 2. County FRANKLIN  
 4. Present Name(s) 334 WALHALLA ROAD

6. Specific Location 334 WALHALLA RD.  
3 W of BRYNHED - N  
 7. City or Town If Rural, Township & Vicinity COLUMBUS  
 8. Site Plan with North Arrow  
  
 9. Coordinates  
 Lat. \_\_\_\_\_ Long. \_\_\_\_\_  
 U.T.M. Reference \_\_\_\_\_  
 10. Site  Building  Structure  Object   
 11. On National Register? Yes  No  12. Is It Eligible? Yes  No   
 13. Part of Estab. Hist. Dist.? Yes  No  14. District Potent'l? Yes  No   
 15. Name of Established District \_\_\_\_\_  
 16. Thematic Category D  
 17. Date(s) or Period 71910 71920 ca (1936-37)  
 18. Style or Design \_\_\_\_\_  
 19. Architect or Engineer \_\_\_\_\_  
 20. Contractor or Builder \_\_\_\_\_  
 21. Original Use, if apparent HOUSG  
 22. Present Use HOUSG  
 23. Ownership Public  Private   
 24. Owner's Name & Address, if known 47056 SOPHIE A PATTERSON SAME  
 25. Open to Public? Yes  No   
 26. Local Contact Person or Organization \_\_\_\_\_  
 27. Other Surveys in Which Included NATIONAL REGISTER  
 28. No. of Stories 25  
 29. Basement? Yes  No   
 30. Foundation Material STONE  
 31. Wall Construction STONE  
 32. Roof Type & Material GABLE SLATE  
 33. No. of Bays Front 10 Side \_\_\_\_\_  
 34. Wall Treatment PLAIN  
 35. Plan Shape IRREGULAR  
 36. Changes (Explain in #42) Addition  Altered  Moved   
 37. Condition Interior \_\_\_\_\_ Exterior GOOD  
 38. Preservation Underway? Yes  No   
 39. Endangered? By What? Yes  No   
 40. Visible from Public Road? Yes  No   
 41. Distance from and Frontage on Road \_\_\_\_\_

42. Further Description of Important Features  
TERRACED GARDEN FACING RAUING  
TURRENT ROOM, BAY WINDOWS, SHED DORMERS



43. History and Significance THIS HOUSE DEALS W/ THE RAUING IN A RATHER SENSITIVE WAY WITH TERRACOS, STAIRS, ETC.

44. Description of Environment and Outbuildings WALHALLA PK PK LOT 94 - THIS HOUSG IS LOCATED ON THE NORTH COGG OF WALHALLA RAUING.

45. Sources of Information COL. CITY DIRECTORIES 1939-38  
 46. Prepared by CS  
 47. Organization CI  
 48. Date 20 AUG 75 49. Revision Date(s) \_\_\_\_\_

5. Other Name(s) \_\_\_\_\_

334 WALHALLA

OHIO HISTORIC INVENTORY

1949

39-40

35-36

36-37

WALHALLA ROAD

UNIVERSITY OF CINCINNATI

28. Basement?	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
29. Foundation Material	STONE	
30. Via Construction	TYPE	
31. Type of Material	GATE	
32. Type of Gate	SIDE	
33. Via Location	SIDE	
34. Via Material	PAVEMENT	
35. Via Shape	RECTANGULAR	
36. Changes	<input type="checkbox"/> Addition <input type="checkbox"/> Altered <input checked="" type="checkbox"/> Moved	
37. Condition	GOOD	
38. Preservation	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
39. Endangered?	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
40. Visible from Public Road?	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>



THE HOUSE IS IN A RATHER GOOD CONDITION. THE HOUSE IS IN A RATHER GOOD CONDITION. THE HOUSE IS IN A RATHER GOOD CONDITION.

THE HOUSE IS IN A RATHER GOOD CONDITION. THE HOUSE IS IN A RATHER GOOD CONDITION. THE HOUSE IS IN A RATHER GOOD CONDITION.

41. Prepared by: [Signature]

42. Organization: [Signature]

43. Date: [Signature]