


OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

1. No. FRA-1672-103	4. Present Name(s) 91 WEST LONGVIEW
2. County FRANKLIN	5. Other Name(s)
3. Location of Negatives O.H.S.	

CODED

1. No. **FRA-1672-103**
2. County **FRANKLIN**
4. Present Name(s) **91 WEST LONGVIEW**

6. Specific Location 91 WEST LONGVIEW	16. Thematic Category 0	28. No. of Stories 1 1/2
7. City or Town If Rural, Township & Vicinity COLUMBUS	17. Date(s) or Period ca 1910-20	29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
8. Site Plan with North Arrow LINTON HIS. AVE. 	18. Style or Design -	30. Foundation Material STONE
9. Coordinates Lat. _____ Long. _____ U.T.M. Reference Zone _____ Easting _____ Northing _____	19. Architect or Engineer -	31. Wall Construction WOOD FRAME
10. Site Building <input checked="" type="checkbox"/> Structure <input type="checkbox"/> Object <input type="checkbox"/>	20. Contractor or Builder -	32. Roof Type & Material GABLET ASH SHINGLE
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	21. Original Use, if apparent HOUSE	33. No. of Bays Front 3 Side 3
12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	22. Present Use HOUSE	34. Wall Treatment EX CLAPBOARD
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>	35. Plan Shape IRREGULAR
14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	24. Owner's Name & Address, if known LAURA M FAGAN SAME	36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/>
15. Name of Established District	25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	37. Condition Interior _____ Exterior FLOOR
42. Further Description of Important Features VERANDA ENCLOSES TWO SIDES ORNATE CORNICE IN THE PORCH DECORATING SHINGLES-WORK IN THE GABLES	26. Local Contact Person or Organization	38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
43. History and Significance	27. Other Surveys in Which Included	39. Endangered? By What? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NEGLECT
44. Description of Environment and Outbuildings PHILLIP LEHMAN ET AL LOT 20; HOUSES ON LONGVIEW ARE VERY CLOSE TO THE STREET AND TO EACH OTHER. GENERALLY SMALL NON-DESCRIPT HOUSES.		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
45. Sources of Information BALST'S PROPERTY ATLAS 1910 " " " 1920		41. Distance from and Frontage on Road 25' X 30'



5. Other Name(s)

46. Prepared by CSJ	
47. Organization CF	
48. Date 20 AUG 75	49. Revision Date(s) 8

51. Condition of Property

- Excellent
- Good/Fair
- Deteriorated
- Ruin
- Destroyed/Burned
- Date _____

52. Historic Outbuildings and Dependencies

Barn Type(s)

- Corn Crib or Shed
- Summer Kitchen
- Silo
- Designed landscape features
- Smoke House
- Spring House
- Ice House
- Privy
- Garage

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	┐
.
.
.
.
.
.
└	.	.	.	┘

42. (Cont'd)

43. (Cont'd)