



OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

<p>1. No. 141 FRA-1839-10</p> <p>2. County FRANKLIN</p> <p>3. Location of Negatives OHS</p>	<p>4. Present Name(s) BOB'S KEY SERVICE.</p> <p>5. Other Name(s) PURE OIL CO.</p>	<p>1. No. 141</p> <p>2. County FRANKLIN</p> <p>4. Present Name(s) BOB'S KEY SHOP.</p> <p>5. Other Name(s) PURE OIL CO.</p>						
<p>6. Specific Location 3535 N. HIGH ST.</p> <p>7. City or Town If Rural, Township & Vicinity COLUMBUS</p> <p>8. Site Plan with North Arrow  </p> <p>9. Coordinates Lat. _____ Long. _____ U.T.M. Reference _____</p> <table border="1" style="width:100%; text-align: center;"> <tr> <td>Zone</td> <td>Easting</td> <td>Northing</td> </tr> <tr> <td> </td> <td> </td> <td> </td> </tr> </table> <p>10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/></p> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>15. Name of Established District _____</p>	Zone	Easting	Northing				<p>16. Thematic Category D 20TH CEN ARCH.</p> <p>17. Date(s) or Period C 1925</p> <p>18. Style or Design TUDOR.</p> <p>19. Architect or Engineer _____</p> <p>20. Contractor or Builder _____</p> <p>21. Original Use, if apparent GARAGE</p> <p>22. Present Use KEY SHOP</p> <p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name & Address, if known ROBERT E. STUDER. 3535 N. HIGH COLUMB. O.</p> <p>25. Open to Public? 8-5:30 Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>26. Local Contact Person or Organization ROB. E. STUDER.</p> <p>27. Other Surveys in Which Included _____</p>	<p>28. No. of Stories 1</p> <p>29. Basement? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>30. Foundation Material STONE</p> <p>31. Wall Construction BRICK</p> <p>32. Roof Type & Material GABLED TILE.</p> <p>33. No. of Bays Front 5 Side 3</p> <p>34. Wall Treatment PLAIN</p> <p>35. Plan Shape L.</p> <p>36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior GOOD Exterior GOOD</p> <p>38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road 25' x 60'</p>
Zone	Easting	Northing						
<p>42. Further Description of Important Features DESIGNED ORIGINALLY AS A FILLING STATION, IT HAS A CANOPY WITH WOOD DETAILS. THE GABLED END IS WOOD & STUCCO. THERE ARE LARGE BRACKETS SUPPORTING THE OVERHANG OF THE ROOF. THE ROOF IS CLAY TILE. THE MAIN WALLS ARE BRICK WITH WOOD FRAME WINDOWS INSET. THERE ARE 2 GARAGE BAYS.</p>								
<p>43. History and Significance WAS ORIGINALLY A PURE OIL STATION. KEY SERVICE TOOK OVER IN 1968. THE PROPERTY WAS BOUGHT BY THE MOORE/OIL CO IN 1924 FROM J.H. CROSHORE - THE PROPERTY WAS SOLD TO PURE IN 1928</p>								
<p>44. Description of Environment and Outbuildings LOCATED IN COMMERCIAL AREA OF HIGH ST. IN CUMTOWNVILLE. BUILDING IS SET BACK FOR CAR ACCESS.</p>								
<p>45. Sources of Information USUAL INSPECTION BOB STUDER OWNER COLUMB. FRANKLIN CO. TAX RECORDS</p>		<p>46. Prepared by HOBSTETTER</p> <p>47. Organization COLUMB. INV.</p> <p>48. Date 8-26-74</p> <p>49. Revision Date(s) _____</p>						

51. Condition of Property

- Excellent
- Good/Fair
- Deteriorated
- Ruin
- Destroyed/Burned
- Date _____

52. Historic Outbuildings and Dependencies

Barn Type(s)

- Corn Crib or Shed
- Summer Kitchen
- Silo
- Designed landscape features
- Smoke House
- Spring House
- Ice House
- Privy
- Garage

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

<input type="checkbox"/>	<input type="checkbox"/>
.
.
.
.
.
.
.
.
<input type="checkbox"/>	<input type="checkbox"/>

42. (Cont'd)

43. (Cont'd)