


OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

1. No. 142 FRA-1840-10		4. Present Name(s) DR. S. CORSON RESIDENCE.		1. No. 142	
2. County FRANKLIN		5. Other Name(s) J. HARVEY ZINN RES.			2. County FRANKLIN
3. Location of Negatives OHS		CODED			
6. Specific Location 285 KENWORTH.		16. Thematic Category D 20TH CEN ARCH.		5. Other Name(s) J. HARVEY ZINN RES.	
7. City or Town If Rural, Township & Vicinity COLUMBUS.		17. Date(s) or Period C 1920			
8. Site Plan with North Arrow 		18. Style or Design			
9. Coordinates Lat. _____ Long. _____ U.T.M. Reference _____		19. Architect or Engineer		28. No. of Stories 2 1/2	
Zone _____ Easting _____ Northing _____		20. Contractor or Builder		29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/>		21. Original Use, if apparent HOUSE		30. Foundation Material STONE	
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		22. Present Use HOUSE.		31. Wall Construction WOOD.	
12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>		32. Roof Type & Material GABLED SHINGLE.	
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		24. Owner's Name & Address, if known DR. CORSON 285 KENWORTH COLUMBUS, OH.		33. No. of Bays Front 10. Side 2	
14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		34. Wall Treatment LAPPED SIDING	
15. Name of Established District		26. Local Contact Person or Organization DR. CORSON.		35. Plan Shape	
42. Further Description of Important Features HOUSE IS WOOD FRAME WITH A SHINGLE ROOF. THERE ARE DORMER WINDOWS ALONG THE GARAGE ROOF AND THE MAIN HOUSE. THERE ARE 2 PORCHES WITH LARGE PORCH WHICH FACES THE RIVER. THERE ARE SEMICIRCULAR FAN PATTERNS OVER SEVERAL OF THE WINDOWS.		27. Other Surveys in Which Included		36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/>	
43. History and Significance PROPERTY WAS OWNED BY J. ZINN FROM 1920-1959 EMMA ZINN 1959-1962 SAMUEL CORSON 1962-		46. Prepared by HOBSTETTER		37. Condition Interior GOOD Exterior GOOD	
44. Description of Environment and Outbuildings LOCATED ALONG OQUANTANGY RIVER. HOUSE IS SET BACK FROM STREET AND SURROUNDED WITH LARGE TREES.				38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
45. Sources of Information VISUAL INSPECTION. FRANKLIN CO TAX RECORDS		47. Organization COLO. INVENTORY.		39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
		48. Date 8/24/75		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
		49. Revision Date(s)		41. Distance from and Frontage on Road 60' x 100'	



5. Other Name(s)
J. HARVEY ZINN RES.

