

OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

<p>1. No. 144 FPA-1842-10</p> <p>2. County FRANKLIN</p> <p>3. Location of Negatives OHS</p>	<p>4. Present Name(s) BENJAMIN WIAINT RESIDENCE.</p> <p>5. Other Name(s) HARRISON NUTTER RES.</p>	<p>1. No. 144</p> <p>2. County FRANKLIN</p> <p>4. Present Name(s) BEN. WIAINT RESIDENCE</p> <p>5. Other Name(s) HARRISON NUTTER RES.</p>										
<p>6. Specific Location 265 KENWORTH.</p> <p>7. City or Town If Rural, Township & Vicinity COLUMBUS.</p> <p>8. Site Plan with North Arrow</p>	<p>16. Thematic Category D 20TH CEN ARCHT.</p> <p>17. Date(s) or Period C 1910</p> <p>18. Style or Design</p> <p>19. Architect or Engineer</p> <p>20. Contractor or Builder</p> <p>21. Original Use, if apparent HOUSE</p> <p>22. Present Use HOUSE</p> <p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name & Address, if known BEN. WIAINT. 265 W. KENWORTH COLUMBUS, OH.</p> <p>25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>26. Local Contact Person or Organization BEN. WIAINT.</p> <p>27. Other Surveys in Which Included</p>	<p>28. No. of Stories 2 1/2</p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material BRICK</p> <p>31. Wall Construction BRICK</p> <p>32. Roof Type & Material GABLED / SHINGLE.</p> <p>33. No. of Bays Front 4 Side 3</p> <p>34. Wall Treatment PLAIN</p> <p>35. Plan Shape RECT</p> <p>36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior GOOD Exterior GOOD.</p> <p>38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road 40' x 80'</p>										
<p>9. Coordinates</p> <p>Lat. _____ Long. _____</p> <p>U.T.M. Reference</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:10%;"></td> <td style="width:10%;"></td> <td style="width:10%;"></td> <td style="width:10%;"></td> <td style="width:10%;"></td> <td style="width:10%;"></td> <td style="width:10%;"></td> <td style="width:10%;"></td> <td style="width:10%;"></td> <td style="width:10%;"></td> </tr> </table> <p>Zone _____ Easting _____ Northing _____</p> <p>10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/></p> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>15. Name of Established District</p>											<p>42. Further Description of Important Features HOUSE IS BRICK CONSTRUCTION WITH WOOD WINDOWS & PORCHES. THE FRONT PORCH HAS DORIC COLUMNS SUPPORTING THE ROOF WITH BRACKETS EXTENDING TO FORM A OVERHANG. BRACKETS ARE ALSO USED ALONG THE SOFFIT OF THE MAIN BODY OF THE ROOF. THERE IS A CARPORT TO THE W. SIDE. THE FRONT HAS FRENCH DOORS OPENING TO A PORCH</p>	
<p>43. History and Significance</p> <table style="width:100%;"> <tr> <td style="width:50%;">OWNED BY HARRISON NUTTER? - 1936</td> <td style="width:50%;">BEN GOLDEN 1962-1969</td> </tr> <tr> <td>ADRIANE PROVENS 1939-1944</td> <td>J. GOLDEN 1969</td> </tr> <tr> <td>EDITH STEIN 1944-1952</td> <td>WM. YOUNG 1969-1973</td> </tr> <tr> <td>B. HAYDEN 1952-1962</td> <td>B. WIAINT 1973</td> </tr> </table>		OWNED BY HARRISON NUTTER? - 1936	BEN GOLDEN 1962-1969	ADRIANE PROVENS 1939-1944	J. GOLDEN 1969	EDITH STEIN 1944-1952	WM. YOUNG 1969-1973	B. HAYDEN 1952-1962	B. WIAINT 1973			
OWNED BY HARRISON NUTTER? - 1936	BEN GOLDEN 1962-1969											
ADRIANE PROVENS 1939-1944	J. GOLDEN 1969											
EDITH STEIN 1944-1952	WM. YOUNG 1969-1973											
B. HAYDEN 1952-1962	B. WIAINT 1973											
<p>44. Description of Environment and Outbuildings LOCATED IN RESIDENTIAL AREA OF CUNTONVILLE. HOMES ARE MOSTLY 60-80 YRS OLD. THERE IS A DETACHED GARAGE TO THE REAR.</p>												
<p>45. Sources of Information VISUAL INF. FRANK. CO. TAX RECORDS.</p>	<p>46. Prepared by HORSTREITER</p> <p>47. Organization COGS. INV.</p> <p>48. Date 8-24-75</p> <p>49. Revision Date(s)</p>											

51. Condition of Property

- | | |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Ruin |
| <input type="checkbox"/> Good/Fair | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____ |

52. Historic Outbuildings and Dependencies

Barn Type(s)

- | | | |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/> | Smoke House <input type="checkbox"/> | Privy <input type="checkbox"/> |
| Summer Kitchen <input type="checkbox"/> | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/> | Ice House <input type="checkbox"/> | |
| Designed landscape features <input type="checkbox"/> | | |

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	┐
.
.
.
.
.
.
└	.	.	.	┘

42. (Cont'd)

43. (Cont'd)