



OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

<p>1. No. <u>145 FRA-1843-10</u></p> <p>2. County <u>FRANKLIN</u></p> <p>3. Location of Negatives <u>OHS</u></p>	<p>4. Present Name(s) <u>MR & MRS JAMES T. ROBERTS.</u></p> <p>5. Other Name(s) <u>WM. SCOTT RESIDENCE.</u></p>	
<p>6. Specific Location <u>203 KENWORTH.</u></p> <p>7. City or Town If Rural, Township & Vicinity <u>COLUMBUS</u></p> <p>8. Site Plan with North Arrow</p>  <p>9. Coordinates Lat. _____ Long. _____ U.T.M. Reference Zone _____ Easting _____ Northing _____</p>	<p>16. Thematic Category <u>D 20TH CEN AREA.</u></p> <p>17. Date(s) or Period <u>1909 (ABSTRACT)</u></p> <p>18. Style or Design <u>LODGE OR CABIN.</u></p> <p>19. Architect or Engineer</p> <p>20. Contractor or Builder</p> <p>21. Original Use, if apparent <u>HOUSE</u></p> <p>22. Present Use <u>HOUSE.</u></p> <p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name & Address, if known <u>CONSTANCE ROBERTS 203 KENWORTH COLS.</u></p> <p>25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>26. Local Contact Person or Organization <u>JAMES ROBERTS</u></p> <p>27. Other Surveys in Which Included</p>	<p>28. No. of Stories <u>2</u></p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material <u>STONE.</u></p> <p>31. Wall Construction <u>WOOD FRAME.</u></p> <p>32. Roof Type & Material <u>GABLED / SHINGLE.</u></p> <p>33. No. of Bays Front <u>5</u> Side <u>5</u></p> <p>34. Wall Treatment <u>LAPPED SIDING</u></p> <p>35. Plan Shape <u>RECT.</u></p> <p>36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input checked="" type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior <u>GOOD</u> Exterior <u>GOOD</u></p> <p>38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road</p>
<p>10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/></p> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>15. Name of Established District</p>	<p>42. Further Description of Important Features <u>HOUSE IS BUILT ON A SMALL HILL WITH THE GARAGE ENTRY BELOW AT BASEMENT LEVEL. THERE ARE 2 PORCHES ON EITHER END. THE LIVING ROOM HAS A LARGE EYE BROWN ARCH WINDOW FACING THE STREET. THERE ARE FRENCH DOORS IN SEVERAL AREAS. THE UPPER FLOOR CONSISTS OF ONE ROOM WHICH LIGHTED BY CLEARSTORY WINDOWS.</u></p>	
<p>43. History and Significance <u>ROBERTS HAVE OWNED THE HOUSE SINCE 1967. HOUSE WAS BOUGHT FROM THE ASHCROFTS WHO LIVED THERE SINCE 1958, BEFORE THIS TIME IT WAS OCCUPIED BY THE HEWITT FAMILY. WILLIAM SCOTT WAS OWNER OF THE PROPERTY AT THE TIME OF CONSTRUCTION.</u></p>		
<p>44. Description of Environment and Outbuildings <u>HOUSE HAS A LARGE SPRUCE TREE AND BALSAM PINE IN THE FRONT YARD. SURROUNDING HOMES ARE SIMILAR AGE.</u></p>		
<p>45. Sources of Information <u>CONSTANCE ROBERTS VISUAL INSP. ABSTRACT.</u></p>	<p>46. Prepared by <u>HOBSTETTER</u></p> <p>47. Organization <u>COLS. INV.</u></p> <p>48. Date <u>8-26-75</u> 49. Revision Date(s)</p>	

1. No. 145
 2. County FRANKLIN
 4. Present Name(s) JAMES ROBERTS RESIDENCE.
 5. Other Name(s) WM. SCOTT RESIDENCE.

51. Condition of Property

- | | |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Ruin |
| <input type="checkbox"/> Good/Fair | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____ |

52. Historic Outbuildings and Dependencies

Barn Type(s)

- | | | |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/> | Smoke House <input type="checkbox"/> | Privy <input type="checkbox"/> |
| Summer Kitchen <input type="checkbox"/> | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/> | Ice House <input type="checkbox"/> | |
| Designed landscape features <input type="checkbox"/> | | |

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	┐
.
.
.
.
.
.
└	.	.	.	┘

42. (Cont'd)

43. (Cont'd)