

# OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office  
Ohio Historical Center  
Columbus, Ohio 43211


1. No. 166 FRA-1844-10 4. Present Name(s) SVOBODA HOME. COPIED

2. County FRANKLIN 5. Other Name(s) C. HOWARD MILLER RESIDENCE.

3. Location of Negatives OHS

6. Specific Location 163 KENWORTH RD 16. Thematic Category D 20TH CEN. ARCH. 28. No. of Stories 2

7. City or Town If Rural, Township & Vicinity COLUMBUS 17. Date(s) or Period C. 1913 29. Basement? Yes  No

8. Site Plan with North Arrow  18. Style or Design 30. Foundation Material STONE

9. Coordinates 19. Architect or Engineer 31. Wall Construction WOOD FRAME

Lat. \_\_\_\_\_ Long. \_\_\_\_\_ 20. Contractor or Builder 32. Roof Type & Material GAR. HIPPED / SHINGLE.

U.T.M. Reference 21. Original Use, if apparent HOUSE 33. No. of Bays Front 3 Side 4

Zone \_\_\_\_\_ Easting \_\_\_\_\_ Northing \_\_\_\_\_ 22. Present Use HOUSE 34. Wall Treatment LAPPED SIDING.

10. Site  Structure  23. Ownership Public  Private  35. Plan Shape RECT.

Building  Object  24. Owner's Name & Address, if known JACQUELYN SVOBODA 36. Changes Addition  (Explain in #42) Altered  Moved

11. On National Register? Yes  No  12. Is It Eligible? Yes  No  37. Condition Interior GOOD Exterior GOOD

13. Part of Estab. Hist. Dist.? Yes  No  14. District Potent'l? Yes  No  38. Preservation Underway? Yes  No

15. Name of Established District 25. Open to Public? Yes  No  39. Endangered? By What? Yes  No

26. Local Contact Person or Organization FRANK SVOBODA 40. Visible from Public Road? Yes  No

27. Other Surveys in Which Included 41. Distance from and Frontage on Road 30' x 60'

42. Further Description of Important Features HOUSE IS WOOD FRAME IN CONSTRUCTION. THERE IS A LARGE PORCH ON THE FRONT SIDE SUPPORTED BY COLUMNS IN PAIRS. WINDOWS ARE WOOD FRAME PLACEMENT & SIZE OF THE WINDOWS VARY. THE ROOF HAS DORMERED WINDOWS ON 3 SIDES. THE DORMERS HAVE THE FRONT OF THE ROOF RIDGE FOLDED DOWN OVER THE WINDOW. THERE IS A SUN ROOM ON THE REAR.

43. History and Significance HOUSE IS ONE OF 2 IDENTICAL IN THE CLINTONVILLE AREA.  
KIBBY KESLER 1910 - 1929  
C. HOWARD MILLER. 1929 - 1974  
SVOBODA 1974 -

44. Description of Environment and Outbuildings LOCATED IN RESIDENTIAL AREA OF CLINTONVILLE, SURROUNDING HOMES ARE SIMILAR IN AGE. THERE IS A BARN TO THE REAR.

45. Sources of Information VISUAL INSP.  
FRANK SVOBODA OWNER.  
ABSTRACT.

46. Prepared by HOBSTETTER

47. Organization COLS. INV.

48. Date 8-26-75 49. Revision Date(s)



1. No. 166

2. County FRANKLIN

4. Present Name(s) SVOBODA RESIDENCE.

5. Other Name(s) C. HOWARD MILLER RES.

51. Condition of Property

- Excellent                       Ruin  
 Good/Fair                       Destroyed/Burned  
 Deteriorated                      Date \_\_\_\_\_

52. Historic Outbuildings and Dependencies

Barn Type(s)

\_\_\_\_\_

\_\_\_\_\_

- Corn Crib or Shed       Smoke House       Privy   
 Summer Kitchen       Spring House       Garage   
 Silo       Ice House   
 Designed landscape features

53. Affiliated OAI Site Number(s) \_\_\_\_\_ one \_\_\_\_\_ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	.	└
.	.	.	.	.	.
.	.	.	.	.	.
.	.	.	.	.	.
.	.	.	.	.	.
.	.	.	.	.	.
.	.	.	.	.	.
.	.	.	.	.	.
└	.	.	.	.	┌

42. (Cont'd)

43. (Cont'd)