



OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

<p>1. No. 150 FRA-1848-10</p> <p>2. County FRANKLIN</p> <p>3. Location of Negatives OHS.</p>	<p>4. Present Name(s) LEBOLD RESIDENCE.</p> <p>5. Other Name(s) MARY RINKER RES.</p>	<p style="writing-mode: vertical-rl; transform: rotate(180deg);">1. No. 150</p> <p style="writing-mode: vertical-rl; transform: rotate(180deg);">2. County FRANKLIN</p> <p style="writing-mode: vertical-rl; transform: rotate(180deg);">4. Present Name(s) LEBOLD RESIDENCE.</p> <p style="writing-mode: vertical-rl; transform: rotate(180deg);">5. Other Name(s) MARY RINKER RES.</p>	<p style="writing-mode: vertical-rl; transform: rotate(180deg);">FPA-1848-10</p>						
<p>6. Specific Location 100 WEBSTER PARK</p>	<p>16. Thematic Category D 20TH CEN ARCH</p> <p>17. Date(s) or Period C 1910.</p> <p>18. Style or Design</p> <p>19. Architect or Engineer</p> <p>20. Contractor or Builder</p> <p>21. Original Use, if apparent HOUSE.</p> <p>22. Present Use HOUSE</p> <p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name & Address, if known MR & MRS LEBOLD 100 WEBSTER PK. COS. O.</p> <p>25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>26. Local Contact Person or Organization MR. KEENE LEBOLD.</p> <p>27. Other Surveys in Which Included</p>	<p>28. No. of Stories 1 1/2</p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material STONE</p> <p>31. Wall Construction WOOD FRAME</p> <p>32. Roof Type & Material GABLED / SHINGLE.</p> <p>33. No. of Bays Front 3 Side 3</p> <p>34. Wall Treatment LAPPED SIDING.</p> <p>35. Plan Shape RECT.</p> <p>36. Changes in #42 Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior GOOD Exterior GOOD</p> <p>38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road 30' x 60'</p>							
<p>7. City or Town If Rural, Township & Vicinity COLUMBUS.</p> <p>8. Site Plan with North Arrow</p> 	<p>9. Coordinates</p> <p>Lat. _____ Long. _____</p> <p>U.T.M. Reference</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:10%; height: 20px;"></td> <td style="width:10%; height: 20px;"></td> <td style="width:10%; height: 20px;"></td> <td style="width:10%; height: 20px;"></td> <td style="width:10%; height: 20px;"></td> <td style="width:10%; height: 20px;"></td> <td style="width:10%; height: 20px;"></td> <td style="width:10%; height: 20px;"></td> </tr> </table> <p>Zone _____ Easting _____ Northing _____</p> <p>10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/></p> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>15. Name of Established District</p>								
<p>42. Further Description of Important Features HOUSE IS WOOD FRAME EXCEPT FOR THE LARGE FRONT PORCH WHICH IS CONSTRUCTED FROM BRICK RUBLE. HOUSE FACADE IS SYMMETRICAL WITH THE ENTRY CENTERED BETWEEN 3 BAY WINDOWS. THE FRONT DOOR HAS LEADED GLASS SIDE LITES. THE SECOND FLOOR WINDOWS ARE CORNERED ON THE FRONT & BACK SIDES.</p>									
<p>43. History and Significance</p> <p>OWNED BY:</p> <p>M. RINKER ?-1933</p> <p>H.C. RINKER 1933-1934</p> <p>R. SCHWARZEL 1934-1957</p> <p>DAVID SPITZ 1957-1970</p> <p>CHAS. WILSON 1970-1975</p> <p>K. LEBOLD 1973-1975</p>									
<p>44. Description of Environment and Outbuildings LOCATED NEAR HIGH STREET IN RESIDENTIAL AREA. SURROUNDING HOMES ARE SIMILAR AGE. THERE ARE SOME LARGE SPECIMEN TREES ON THE SITE</p>									
<p>45. Sources of Information VISUAL INSP. MRS. LEBOLD. FR. CO. TAX RECORDS</p>	<p>46. Prepared by HOBSTETTER</p> <p>47. Organization COS. INV.</p> <p>48. Date 8-26-75</p> <p>49. Revision Date(s)</p>								

CODED

51. Condition of Property

- | | |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Ruin |
| <input type="checkbox"/> Good/Fair | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____ |

52. Historic Outbuildings and Dependencies

Barn Type(s)

- | | | |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/> | Smoke House <input type="checkbox"/> | Privy <input type="checkbox"/> |
| Summer Kitchen <input type="checkbox"/> | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/> | Ice House <input type="checkbox"/> | |
| Designed landscape features <input type="checkbox"/> | | |

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	└
.
.
.
.
.
.
.
└	┌

42. (Cont'd)

43. (Cont'd)