



OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

1. No. 151. FRA-1849-10	4. Present Name(s) H. CREEK RESIDENCE	CODED	FRA-1849-10	1. No. 15	
2. County FRANKLIN	5. Other Name(s) BARTON RESIDENCE.				2. County FRANKLIN
3. Location of Negatives OHS.					

6. Specific Location 213 WEBSTER PARK	16. Thematic Category D 20TH CEN ARCH	28. No. of Stories 1 1/2
	17. Date(s) or Period 6 1909.	29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
7. City or Town, If Rural, Township & Vicinity COLUMBUS.	18. Style or Design VERNACULAR.	30. Foundation Material STONE
8. Site Plan with North Arrow 	19. Architect or Engineer	31. Wall Construction WOOD FRAME
	20. Contractor or Builder	32. Roof Type & Material GABLED / SHINGLE.
9. Coordinates Lat. _____ Long. _____ U.T.M. Reference Zone _____ Easting _____ Northing _____	21. Original Use, if apparent HOUSE	33. No. of Bays Front 3 Side 3
	22. Present Use HOUSE	34. Wall Treatment LAPPED SIDING.
10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/>	23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>	35. Plan Shape RECT.
	24. Owner's Name & Address, if known MR & MRS H. CREEK 213 WEBSTER PK. COLS. O.	36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/>
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	37. Condition Interior GOOD Exterior GOOD
12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	26. Local Contact Person or Organization MR. H. CREEK.	38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	27. Other Surveys in Which Included	39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
15. Name of Established District		41. Distance from and Frontage on Road 35' x 60'

42. Further Description of Important Features HOUSE IS WOOD FRAME IN CONSTRUCTION. THERE IS A LARGE FRONT PORCH WITH A LARGE BAY WINDOW ON EITHER SIDE OF THE MAIN ENTRY. A LARGE DORMERED WINDOW IS ABOVE THE MAIN ENTRY. WINDOWS ARE 8/8 DOUBLE HUNG AND CASEMENT. THE MAIN ENTRY DOOR HAS SIDE LITES.		5. Other Name(s) BARTON RESIDENCE.
--	---	--

43. History and Significance ORIGINALLY A FARM HOUSE WITH LAND TO THE WEST & SOUTH. WAS ONE OF THE FIRST HOMES IN THE AREA.
R. LULL 1946 - 1953 R. RUPP 1953 - 1961 N. USTICK ? - 1928, BARTONS, 1961 - 1968. WM USTICK 1928-46 H. CREEK 1968 -

44. Description of Environment and Outbuildings LOCATED NEAR OLENTANGY RIVER IN CLINTONVILLE. HOUSE HAS A SEPERATE GARAGE IN REAR.
--

45. Sources of Information VISUAL INSP. MRS. CREEK FRANK. CO. TAX RECORDS.	46. Prepared by HOBSTETTER
	47. Organization COLS. INV.
	48. Date 8-26.
	49. Revision Date(s)

51. Condition of Property

- Excellent Ruin
 Good/Fair Destroyed/Burned
 Deteriorated Date _____

52. Historic Outbuildings and Dependencies

Barn Type(s)

- Corn Crib or Shed Smoke House Privy
 Summer Kitchen Spring House Garage
 Silo Ice House
 Designed landscape features

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	└
.
.
.
.
.
.
└	.	.	.	└

42. (Cont'd)

43. (Cont'd)