

OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

<p>1. No. <u>161 FPA-1859-10</u></p> <p>2. County <u>FRANKLIN</u></p> <p>3. Location of Negatives <u>OHs.</u></p>	<p>4. Present Name(s) <u>E. H. LOCKRIDGE RESIDENCE</u></p> <p>5. Other Name(s) <u>PAUL BOGATAY RESIDENCE.</u></p>	<p>1. No. <u>161</u></p> <p>2. County <u>FRANKLIN</u></p> <p>4. Present Name(s) <u>E. H. LOCKRIDGE RESIDENCE.</u></p> <p>5. Other Name(s) <u>PAUL BOGATAY RESIDENCE.</u></p>										
<p>6. Specific Location <u>45 WEISHEIMER</u></p>	<p>16. Thematic Category <u>D 20TH CEN. ARCH</u></p> <p>17. Date(s) or Period <u>C. 1905</u></p> <p>18. Style or Design</p> <p>19. Architect or Engineer</p> <p>20. Contractor or Builder</p> <p>21. Original Use, if apparent <u>HOUSE</u></p> <p>22. Present Use <u>HOUSE</u></p> <p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name & Address, if known <u>E. H. LOCKRIDGE 45 WEISHEIMER. COLS. O.</u></p> <p>25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>26. Local Contact Person or Organization <u>MR. LOCKRIDGE</u></p> <p>27. Other Surveys in Which Included</p>	<p>28. No. of Stories <u>2</u></p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material <u>STONE</u></p> <p>31. Wall Construction <u>WOOD FRAME</u></p> <p>32. Roof Type & Material <u>GABLED SHINGLE</u></p> <p>33. No. of Bays Front <u>3</u> Side</p> <p>34. Wall Treatment <u>LAPPED SIDING.</u></p> <p>35. Plan Shape <u>RECT.</u></p> <p>36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input checked="" type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior <u>GOOD</u> Exterior <u>GOOD</u></p> <p>38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road <u>60' x 120'</u></p>										
<p>7. City or Town If Rural, Township & Vicinity <u>COLUMBUS</u></p> <p>8. Site Plan with North Arrow</p>	<p>9. Coordinates</p> <p>Lat. _____ Long. _____</p> <p>U.T.M. Reference</p> <table border="1" style="width:100%; text-align: center;"> <tr> <td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td> </tr> </table> <p>Zone _____ Easting _____ Northing _____</p> <p>10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/></p> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>15. Name of Established District</p>											
<p>42. Further Description of Important Features <u>HOUSE IS CONSTRUCTED OF WOOD. LAPPED SIDING IS USED ON THE LOWER PORTION. LAPPED SHAKES IN THE GABLE AREAS. THERE IS A LARGE PORCH ON THE FRONT WITH FRENCH DOORS ON EITHER SIDE OF THE MAIN ENTRY. A ROOM HAS BEEN ADDED RECENTLY ON THE REAR. ON THE SECOND FLOOR THERE IS AN ENCLOSED PORCH WHICH FACES THE SOUTH. A LONG SHED DORMER IS INSET IN THE ROOF.</u></p>												
<p>43. History and Significance</p> <p style="text-align: center;"><u>ELIZ. KAUFMAN ?-1929</u> <u>FRED HALL 1929-1936</u> <u>P & J. BOGATAY 1936-1971</u> <u>ERNEST LOCKRIDGE 1971 -</u></p>												
<p>44. Description of Environment and Outbuildings <u>LOCATED NEAR HIGH ST. IN RESIDENTIAL AREA, SURROUNDING HOMES ARE GENERALLY OF A LATER PERIOD. THERE IS A DETACHED GARAGE TO THE REAR.</u></p>												
<p>45. Sources of Information</p> <p><u>VISUAL INSP.</u> <u>FRANKLIN CO. TAX RECORDS.</u> <u>FRANK. CO. TAX RECORDS.</u></p>		<p>46. Prepared by <u>HOBSTETTER</u></p> <p>47. Organization <u>COLS INV.</u></p> <p>48. Date <u>8-27-75</u></p> <p>49. Revision Date(s)</p>										

51. Condition of Property

- | | |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Ruin |
| <input type="checkbox"/> Good/Fair | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____ |

52. Historic Outbuildings and Dependencies

Barn Type(s)

- | | | |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/> | Smoke House <input type="checkbox"/> | Privy <input type="checkbox"/> |
| Summer Kitchen <input type="checkbox"/> | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/> | Ice House <input type="checkbox"/> | |
| Designed landscape features <input type="checkbox"/> | | |

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	┐
.
.
.
.
.
.
└	.	.	.	┘

42. (Cont'd)

43. (Cont'd)