

OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211


1. No. 162 FPA-1860-10 4. Present Name(s) MRS MARGARET URBAN. RESIDENCE

2. County FRANKLIN 5. Other Name(s)

3. Location of Negatives OHHS

6. Specific Location 4475 N. HIGH ST. 16. Thematic Category D 20TH CEN ARCH. 28. No. of Stories 1 1/2

7. City or Town If Rural, Township & Vicinity COLUMBUS. 17. Date(s) or Period C 19. 29. Basement? Yes No

8. Site Plan with North Arrow  18. Style or Design ENGLISH COTTAGE. 30. Foundation Material STONE

19. Architect or Engineer 31. Wall Construction STONE.

20. Contractor or Builder 32. Roof Type & Material HIPPED SHINGLE

21. Original Use, if apparent HOUSE 33. No. of Bays Front 3 Side 3

22. Present Use HOUSE 34. Wall Treatment ROUGH STONE

23. Ownership Public Private 35. Plan Shape IRREG.

24. Owner's Name & Address, if known MRS. MARGARET URBAN. 4475 N. HIGH ST. COLS. O. 36. Changes (Explain in #42) Addition Altered Moved

37. Condition Interior GOOD Exterior GOOD

9. Coordinates Lat. _____ Long. _____ U.T.M. Reference _____

10. Zone _____ Easting _____ Northing _____

11. On National Register? Yes No 12. Is It Eligible? Yes No

13. Part of Estab. Hist. Dist.? Yes No 14. District Potent'l? Yes No

15. Name of Established District _____

25. Open to Public? Yes No 26. Local Contact Person or Organization MRS. URBAN.

27. Other Surveys in Which Included _____

38. Preservation Underway? Yes No 39. Endangered? By What? Yes No

40. Visible from Public Road? Yes No 41. Distance from and Frontage on Road 30' x 90'

42. Further Description of Important Features HOUSE IS CONSTRUCTED OF STONE OF IRREGULAR SIZES AND SHAPES. THE ROOF IS COVERED WITH SHAKES. THERE IS A SMALL TOWER OVER THE N.E. CORNER ENTRY WHICH IS CAPPED WITH A WEATHER VANE. THERE IS ALSO AN ARCHED SECTION IN THE ROOF WHICH IS OVER A LARGE WINDOWS. WINDOWS ARE STEEL & SILLS ARE STONE.

43. History and Significance PROPERTY HAS BEEN OWNED BY MRS URBAN SINCE 1938 WHEN THE HOUSE WAS BUILT.



44. Description of Environment and Outbuildings LOCATED ON HIGH ST. IN MIXED COMMERCIAL/OFFICE AREA. RESIDENTIAL AREA IS LOCATED TO THE WEST. THE AREA IMMEDIATELY AROUND THE HOUSE IS HEAVILY PLANTED.

45. Sources of Information VISUAL INSPECTION. FRANKLIN CO. TAX RECORDS.

46. Prepared by HOBSTETTER 47. Organization COLS. INV.

48. Date 8-27-75 49. Revision Date(s)

1. No. 162
2. County FRANKLIN
4. Present Name(s) M. URBAN RESIDENCE
5. Other Name(s)

51. Condition of Property

- Excellent Ruin
 Good/Fair Destroyed/Burned
 Deteriorated Date _____

52. Historic Outbuildings and Dependencies

Barn Type(s)

- Corn Crib or Shed Smoke House Privy
 Summer Kitchen Spring House Garage
 Silo Ice House
 Designed landscape features

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	└
.
.
.
.
.
.
└	.	.	.	└

42. (Cont'd)

43. (Cont'd)