



OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

<p>1. No. <u>163 FPA-1861-70</u></p> <p>2. County <u>FRANKLIN</u></p> <p>3. Location of Negatives <u>OLS</u></p>	<p>4. Present Name(s) <u>B. KANOSKI RESIDENCE</u></p> <p>5. Other Name(s) <u>FLORENCE BULFORD RESIDENCE.</u></p>	<p>1. No. <u>163</u></p> <p>2. County <u>FRANKLIN</u></p> <p>4. Present Name(s) <u>KANOSKI RESIDENCE.</u></p> <p>5. Other Name(s) <u>FLORENCE BULFORD RES.</u></p>
<p>6. Specific Location <u>4765 N. HIGH ST.</u></p> <p>7. City or Town <u>COLUMBUS</u> If Rural, Township & Vicinity</p> <p>8. Site Plan with North Arrow  </p> <p>9. Coordinates Lat. _____ Long. _____ U.T.M. Reference [] </p> <p>10. Zone _____ Easting _____ Northing _____ Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/> </p> <p>11. On National Register? Yes <input type="checkbox"/> No <input type="checkbox"/> 12. Is It Eligible? Yes <input type="checkbox"/> No <input type="checkbox"/> 13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input type="checkbox"/> 14. District Potent'l? Yes <input type="checkbox"/> No <input type="checkbox"/> 15. Name of Established District _____ </p>	<p>16. Thematic Category <u>D 20TH CEN. ARCH.</u></p> <p>17. Date(s) or Period _____</p> <p>18. Style or Design _____</p> <p>19. Architect or Engineer _____</p> <p>20. Contractor or Builder _____</p> <p>21. Original Use, if apparent <u>HOUSE</u></p> <p>22. Present Use <u>HOUSE</u></p> <p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name & Address, if known <u>BARBARA KANOWSKI</u> <u>4765 N. HIGH</u> <u>COLS. O.</u></p> <p>25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>26. Local Contact Person or Organization <u>BARBARA KANOWSKI</u></p> <p>27. Other Surveys in Which Included <u>NATIONAL REGISTER</u></p>	<p>28. No. of Stories <u>1 1/2</u></p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material <u>STONE</u></p> <p>31. Wall Construction <u>WOOD FRAME.</u></p> <p>32. Roof Type & Material <u>GABLED SHINGLE</u></p> <p>33. No. of Bays Front <u>3</u> Side _____</p> <p>34. Wall Treatment <u>LAPPED SIDING.</u></p> <p>35. Plan Shape <u>RECT.</u></p> <p>36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior <u>GOOD</u> Exterior <u>GOOD</u></p> <p>38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road <u>40' x 100'</u></p>
<p>42. Further Description of Important Features HOUSE IS CONSTRUCTED OF WOOD ON STONE FOUNDATION. THERE IS A LARGE OVERHANG FORMING A PORCH ON THE SOUTH SIDE WHICH IS THE MAIN ENTRY. THE OVERHANG IS SUPPORTED BY LARGE BRACKETS ON EITHER SIDE OF THE DOOR IS A DORIC COLUMN OF WOOD. THE FACADE IS SYMMETRICAL WITH TRIPLE CASEMENT WINDOWS ON EITHER SIDE THERE IS A SITED DORMER OVER THE ENTRANCE. ALSO AT THE N.E. CORNER IS ANOTHER PORCH. </p>		<p>5. Other Name(s) <u>FLORENCE BULFORD RES.</u></p>
<p>43. History and Significance HOUSE WAS OWNED BY FLORENCE BULFORD UNTIL 1962 WHEN IT WAS SOLD TO THE KANOSKI </p>	<p>44. Description of Environment and Outbuildings LOCATED NEAR HIGH ST. NEAR ENTRANCE TO THE BEECHWOOD AREA. THERE IS A HEAVY PLANTING STRIP BETWEEN HIGH ST AND THE HOUSE THERE IS A DETACHED GARAGE ON THE N. SIDE OF THE HOUSE. </p>	
<p>45. Sources of Information VISUAL INSPECTION. FRANKLIN CO. TAX RECORDS. </p>	<p>46. Prepared by <u>HOBSTETTER</u></p> <p>47. Organization <u>COLS. INV.</u></p> <p>48. Date <u>8-27</u> 49. Revision Date(s) _____</p>	

51. Condition of Property

- | | |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Ruin |
| <input type="checkbox"/> Good/Fair | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____ |

52. Historic Outbuildings and Dependencies

Barn Type(s)

- | | | |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/> | Smoke House <input type="checkbox"/> | Privy <input type="checkbox"/> |
| Summer Kitchen <input type="checkbox"/> | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/> | Ice House <input type="checkbox"/> | |
| Designed landscape features <input type="checkbox"/> | | |

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	└
.
.
.
.
.
.
└	.	.	.	└

42. (Cont'd)

43. (Cont'd)