



OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

<p>1. No. 164. FPA-1862-70</p> <p>2. County FRANKLIN</p> <p>3. Location of Negatives OHS.</p>	<p>4. Present Name(s) JACK SMITH RESIDENCE</p> <p>5. Other Name(s) MCDONALD RESIDENCE.</p>	<p>CODE</p> <p style="writing-mode: vertical-rl; transform: rotate(180deg);">FPA-1862-70</p>	<p>1. No. 164</p> <p>2. County FRANKLIN</p> <p>4. Present Name(s) JACK SMITH RESIDENCE</p> <p>5. Other Name(s) MCDONALD RESIDENCE.</p>				
<p>6. Specific Location 100 W BEECHWOOD</p>	<p>16. Thematic Category D 20TH CEN ARCH</p> <p>17. Date(s) or Period C 1920.</p>	<p>28. No. of Stories 2</p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material STONE</p> <p>31. Wall Construction STUCCO.</p> <p>32. Roof Type & Material HIPPED SHINGLE.</p> <p>33. No. of Bays Front 5 Side 3</p> <p>34. Wall Treatment BELTED.</p> <p>35. Plan Shape SYMM/W WINGS.</p> <p>36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior GOOD Exterior GOOD</p> <p>38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road 30' x 100'</p>	<p>1. No. 164</p> <p>2. County FRANKLIN</p> <p>4. Present Name(s) JACK SMITH RESIDENCE</p> <p>5. Other Name(s) MCDONALD RESIDENCE.</p>				
<p>7. City or Town If Rural, Township & Vicinity COLUMBUS</p> <p>8. Site Plan with North Arrow</p> 	<p>18. Style or Design</p> <p>19. Architect or Engineer</p> <p>20. Contractor or Builder MCDONALD SISTER.</p> <p>21. Original Use, if apparent HOUSE</p> <p>22. Present Use HOUSE</p> <p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name & Address, if known JACK SMITH 100 W. BEECHWOOD COS. O.</p> <p>25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>26. Local Contact Person or Organization JACK SMITH.</p> <p>27. Other Surveys in Which Included</p>						
<p>9. Coordinates Lat. _____ Long. _____ U.T.M. Reference</p> <table border="1" style="width:100%; height: 20px;"> <tr> <td style="width: 25%;">Zone</td> <td style="width: 25%;">Easting</td> <td style="width: 25%;">Northing</td> <td style="width: 25%;"></td> </tr> </table> <p>10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/></p> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>15. Name of Established District</p>	Zone	Easting	Northing				
Zone	Easting	Northing					
<p>42. Further Description of Important Features HOUSE HAS STUCCO EXTERIOR. FACADE IS SYMMETRICAL IN MASSING. THERE IS A SEMI-CIRCULAR ARCHED PORTICO OVER THE MAIN ENTRY. THE HOUSE HAS SEVERAL SETS OF FRENCH DOORS. THE ROOF HAS A 3'-0" SOFFIT OF WOOD WHICH IS DIVIDED INTO PANELS. THERE IS A HORIZONTAL BAND WHICH IS AT THE SECOND FLOOR LEVEL. A GARAGE IS ATTACHED TO THE REAR.</p>							
<p>43. History and Significance ONE OF THE OLDEST HOMES IN THE BEECHWOOD AREA. AT ONE TIME THERE WAS A SMALL ZOO. MCDONALDS C 1920-1946. (HIGH ST. DRESS SHOP OWNERS) TURNER 1946-1961 J. SMITHS 1961-</p>							
<p>44. Description of Environment and Outbuildings LOCATED IN BEECHWOOD AREA, SURROUNDING AREA IS HEAVILY WOODED SURROUNDING HOMES WERE BUILT AT ABOUT THE SAME TIME.</p>							
<p>45. Sources of Information VISUAL INSPECTION MRS. SMITH.</p>	<p>46. Prepared by HOBSTETTER</p> <p>47. Organization COS INV</p> <p>48. Date 8-27-70 49. Revision Date(s)</p>						

51. Condition of Property

- | | |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Ruin |
| <input type="checkbox"/> Good/Fair | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____ |

52. Historic Outbuildings and Dependencies

Barn Type(s)

- | | | |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/> | Smoke House <input type="checkbox"/> | Privy <input type="checkbox"/> |
| Summer Kitchen <input type="checkbox"/> | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/> | Ice House <input type="checkbox"/> | |
| Designed landscape features <input type="checkbox"/> | | |

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	┐
.
.
.
.
.
.
└	.	.	.	┘

42. (Cont'd)

43. (Cont'd)