



# OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office  
Ohio Historical Center  
Columbus, Ohio 43211

<p>1. No. <u>165 FPA-1863-10</u></p> <p>2. County <u>FRANKLIN</u></p> <p>3. Location of Negatives <u>OHS.</u></p>	<p>4. Present Name(s) <u>WM. MILLIGAN RESIDENCE.</u></p> <p>5. Other Name(s) <u>LEAH HULLIBLON RESIDENCE.</u></p>	<p>1. No. <u>165</u></p> <p>2. County <u>FRANKLIN</u></p> <p>4. Present Name(s) <u>WM. MILLIGAN RESIDENCE.</u></p> <p>5. Other Name(s) <u>LEAH HULLIBLON RES.</u></p>
<p>6. Specific Location <u>150 W. BEECHWOOD.</u></p>	<p>16. Thematic Category <u>D 20TH CEN ARCH.</u></p> <p>17. Date(s) or Period <u>C 1920</u></p> <p>18. Style or Design</p> <p>19. Architect or Engineer</p> <p>20. Contractor or Builder</p> <p>21. Original Use, if apparent <u>HOUSE</u></p> <p>22. Present Use <u>HOUSE</u></p> <p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name &amp; Address, if known <u>WM. MILLIGAN RESIDENCE 150 W. BEECHWOOD. COLS. O.</u></p> <p>25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>26. Local Contact Person or Organization <u>WM MILLIGAN.</u></p> <p>27. Other Surveys in Which Included  <b>NATIONAL REGISTER</b></p>	<p>28. No. of Stories <u>2</u></p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material <u>STONE</u></p> <p>31. Wall Construction <u>STONE/WOOD FRAME.</u></p> <p>32. Roof Type &amp; Material <u>HIPPED SHINGLE</u></p> <p>33. No. of Bays Front <u>4</u> Side <u>5</u></p> <p>34. Wall Treatment <u>ROUGH STONE/LAPPED SIDING.</u></p> <p>35. Plan Shape <u>L</u></p> <p>36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior <u>GOOD</u> Exterior <u>GOOD</u></p> <p>38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road <u>60' X 120'</u></p>
<p>7. City or Town If Rural, Township &amp; Vicinity <u>COLUMBUS.</u></p> <p>8. Site Plan with North Arrow</p> 	<p>9. Coordinates Lat. _____ Long. _____ U.T.M. Reference Zone _____ Easting _____ Northing _____</p> <p>10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/></p> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>15. Name of Established District</p>	
<p>42. Further Description of Important Features <u>LOWER HALF OF THE HOUSE IS CONSTRUCTED OF LIMESTONE THE UPPER HALF OF LAPPED WOOD SIDING. THE HOUSE HAS A GREEN SHINGLE HIPPED ROOF WITH HIPPED DORMERS. THERE IS A PORCH AT THE SOUTH END OF THE HOUSE CONSTRUCTED OF STONE. THERE ARE SEVERAL SETS OF FRENCH DOORS. WINDOWS ARE CASEMENT TYPE. THE ENTRY AREA IS COVERED AND HAS 2 SEMI-CIRCULAR ARCHES SUPPORTED BY A STONE COLUMN (DORIC STYLE).</u></p>		
<p>43. History and Significance <u>THE BARN ON THE PROPERTY WAS ONCE A PART OF THE OLD ZOO. PROPERTY WAS OWNED BY: LEAH HULLIBLON 1921-24 ROY SMITH 1924-1959 C. JONES 1959-1969 PHYLIS JONES 1969-1970 MILLIGAN'S 1970-</u></p>		
<p>44. Description of Environment and Outbuildings <u>LOCATED IN BEECHWOOD AREA. SITE HAS SOME LARGE SPECIMAN PINES AND DECIDUOUS TREES. THERE IS AN UNATTACHED GARAGE TO THE WEST</u></p>		
<p>45. Sources of Information <u>VISUAL INSPECT. FRANKLIN CO. TAX RECORDS.</u></p>	<p>46. Prepared by <u>HOBSTETTER</u></p> <p>47. Organization <u>COLS. INV.</u></p> <p>48. Date <u>8-29</u></p> <p>49. Revision Date(s)</p>	

51. Condition of Property

- |                                       |   |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent    | <input type="checkbox"/> Ruin             |
| <input type="checkbox"/> Good/Fair    | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____                                |

52. Historic Outbuildings and Dependencies

Barn Type(s)

---



---

- |  |                                       |                                 |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/>           | Smoke House <input type="checkbox"/>  | Privy <input type="checkbox"/>  |
| Summer Kitchen <input type="checkbox"/>              | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/>                        | Ice House <input type="checkbox"/>    |                                 |
| Designed landscape features <input type="checkbox"/> |                                       |                                 |

53. Affiliated OAI Site Number(s) \_\_\_\_\_ one \_\_\_\_\_ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	.	└
.	.	.	.	.	.
.	.	.	.	.	.
.	.	.	.	.	.
.	.	.	.	.	.
.	.	.	.	.	.
.	.	.	.	.	.
└	.	.	.	.	└

42. (Cont'd)

43. (Cont'd)