





OHIO HISTORIC INVENTORY

1. No. 104 FRA-3785-10		4. Present Name(s) THE PIERCE RESIDENCE		1. No. 3785-10	
2. County FRANKLIN		5. Other Name(s) IN THE PIERCE FAMILY SINCE 1920, DOLL			2. County FRANKLIN
3. Location of Negatives O.H.S.					
6. Specific Location 77 E.N. BROADWAY		16. Thematic Category " D "		28. No. of Stories 3+	
7. City or Town If Rural, Township & Vicinity COLUMBUS		17. Date(s) or Period 1922		29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
8. Site Plan with North Arrow 		18. Style or Design GEORGIAN COLONIAL - PALLADIAN		30. Foundation Material POURED CONCRETE	
9. U.T.M. Reference 17 32 81 83 44 33 03 1		19. Architect or Engineer MR. DOLL		31. Wall Construction BRICK BEARING	
Zone Easting Northing		20. Contractor or Builder		32. Roof Type & Material HIP-SLATE OVER COTTER	
10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/>		21. Original Use, if apparent RESIDENCE		33. No. of Bays Front 3 Side 1	
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		22. Present Use RESIDENCE		34. Wall Treatment BRICK	
12. Is It Eligible? Yes <input type="checkbox"/> No <input type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>		35. Plan Shape SQUARE	
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		24. Owner's Name & Address, if known AS ABOVE		36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/>	
14. District Potent'l? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		37. Condition Interior EXCELLENT Exterior EXCELLENT	
15. Name of Established District NONE		26. Local Contact Person or Organization O.H.S.		38. Preservation Underway? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
42. Further Description of Important Features (Continue on reverse if necessary) THE HOUSE IS IN ORIGINAL CONITION BEING WELL MAINTAINED. IS THE BEST OF ITS STYLE IN THE IMMEDIATE AREA. PORCH ON SIDE ADDS TO THE OVERALL "PALLADIAN" CHARACTER. DETAILING IS CAREFULLY THOUGHT OUT HAVING EAVE-TRELLIS WORK AROUND PORCH.		27. Other Surveys in Which Included NONE.		39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
43. History and Significance THE ARCHITECT DOLL DESIGNED THIS HOME & TWO OTHERS IN SEQUENCE ON N. BROADWAY. THIS WAS HIS BEST EFFORT, A VERY INTEGRAL PIECE OF THE STREETS ARCHITECTURE.				40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
44. Description of Environment and Outbuildings ON SOUTH SIDE OF THE TREE LINED N. BROADWAY STREET OPPOSITE UNITED METHODIST CHURCH. VERY CLEAN SIMPLE LANDSCAPE. ESTABLISHED NEIGHBORHOOD IN BACK ARE THE GARAGE AND A WROUGHT-IRON GAZEBO (SMALL)				41. Distance from and Frontage on Road 63' - 81'	
45. Sources of Information MR. PIERCE, VISUAL INSPECTION		46. Prepared by DAVID W. VARNISH		5. Other Name(s)	
		47. Organization O.S.D.			
		48. Date 8.25.84			
		49. Revision Date(s)			

50. House Type No.

Code No. Name

51. Historic Outbuildings and Dependencies

Barn Type(s)

Code No. Type

Corn Crib or Shed Silo Summer Kitchen Smoke House, Spring House or Ice House Privy Carriage House

Other _____

52. Archaeological Site on Property?

Yes
No

Basis for Information

Owner Collection
Above Ground Earthworks or Mound
Cultural Materials Noted OAI No. _____

53. Farmstead Plan



54. Photo

Roll No. _____ Picture No(s). _____

42. (Cont'd)