




OHIO HISTORIC INVENTORY

1. No. <u>105 FRA-3787-10</u>		4. Present Name(s) <u>CURRENTLY FOR RENT - CENTURY 21 MARK DIVINE</u>		3787-10						
2. County <u>FRANKLIN</u>		5. Other Name(s) <u>JACKSON, DAVIS</u>			2. County FRANKLIN					
3. Location of Negatives <u>O.H.S.</u>						4. Present Name(s)				
6. Specific Location <u>155 E.N. BROADWAY</u>		16. Thematic Category " <u>D</u> "		28. No. of Stories <u>2</u>						
7. City or Town If Rural, Township & Vicinity <u>COLUMBUS</u>		17. Date(s) or Period <u>1915-1923</u>		29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>						
8. Site Plan with North Arrow 		18. Style or Design <u>SECOND EMPIRE</u>		30. Foundation Material <u>BRICK</u>						
9. U.T.M. Reference <table border="1" data-bbox="714 21 763 766"> <tr><td>17</td><td>328290</td><td>4433031</td></tr> <tr><td>Zone</td><td>Easting</td><td>Northing</td></tr> </table>		17	328290	4433031	Zone	Easting	Northing	19. Architect or Engineer <u>MR. MARTIN</u>		31. Wall Construction <u>BRICK BEARING</u>
17	328290	4433031								
Zone	Easting	Northing								
10. Site <input type="checkbox"/> Building <input checked="" type="checkbox"/> Structure <input type="checkbox"/> Object <input type="checkbox"/>		20. Contractor or Builder <u>MARTIN</u>		32. Roof Type & Material <u>MANSARD - WOOD SHAKE</u>						
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		21. Original Use, if apparent <u>RESIDENCE</u>		33. No. of Bays Front Side						
12. Is It Eligible? Yes <input type="checkbox"/> No <input type="checkbox"/>		22. Present Use <u>RESIDENCE</u>		34. Wall Treatment <u>BRICK, CORNICE LINE, DENTILS</u>						
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>		35. Plan Shape <u>SQUARE</u>						
14. District Potent'l? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		24. Owner's Name & Address, if known		36. Changes (Explain in #42) Addition <input checked="" type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/>						
15. Name of Established District <u>NONE</u>		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		37. Condition Interior <u>VERY GOOD</u> Exterior <u>VERY GOOD</u>						
16. Further Description of Important Features (Continue on reverse if necessary) <u>A PORCH HAS BEEN ADDED TO THE REAR OF BUILDING. THE CORNICE LINE IS NICELY DETAILED, HOWEVER OVERALL IS ELEGANT IN ITS SIMPLICITY. THE ROOF AND ITS INHERENT VIRTUES IS THE PROPERTIES MOST IMPORTANT FEATURE.</u>		26. Local Contact Person or Organization <u>O.H.S.</u>		38. Preservation Underway? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>						
17. History and Significance <u>ANOTHER OF THE MARTIN HOMES ON THE STREET, SHOWING A DIVERSITY IN HIS EARLY WORK; HAS UNDERWENT SEVERAL FACELIFTS IN PAST TWENTY YEARS, CURRENTLY IS BACK TO ITS SIMPLEST AND MOST ATTRACTIVE SELF. SIGNIFICANT IN HAVING THE ONLY MANSARDIAN ROOF ON THE STREET, GOOD, SIMPLE EXAMPLE OF THIS STYLE.</u>		27. Other Surveys in Which Included <u>NONE</u>		39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>						
18. Description of Environment and Outbuildings <u>VERY MUCH PART OF THE OVERALL ARCHITECTURAL RESOURCES OF THE ESTABLISHED RESIDENTIAL DISTRICT. GARAGE IS DETACHED AND BEING REPAIRED.</u>		28. Other Surveys in Which Included		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>						
19. Sources of Information <u>MRS. BAUROTH 160 E.N. BROADWAY, VISUAL INSPECTION OWNER</u>		29. Other Surveys in Which Included		41. Distance from and Frontage on Road <u>81' - 50'</u>						
20. Prepared by <u>DAVID W. VARNISH</u>		30. Other Surveys in Which Included		5. Other Name(s)						
21. Organization <u>O.S.U.</u>		31. Other Surveys in Which Included								
22. Date <u>8-25-84</u>		32. Other Surveys in Which Included								
23. Revision Date(s)		33. Other Surveys in Which Included								



50. House Type No.

Code No. Name

51. Historic Outbuildings and Dependencies

Barn Type(s)

Code No. Type

Corn Crib or Shed Smoke House, Privy
Silo Spring House Carriage House
Summer Kitchen or Ice House

Other _____

52. Archaeological Site on Property?

Yes
No

Basis for Information

Owner Collection
Above Ground Earthworks or Mound
Cultural Materials Noted OAI No. _____

53. Farmstead Plan



54. Photo

Roll No. _____ Picture No(s). _____

42. (Cont'd)