




OHIO HISTORIC INVENTORY

| | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---------|---|----------------------|---|-----------------------|------------------------------------|--|--|--|--|--|------|---------|----------|--|--|--|--|--|--|--|--------------------------------------|--|--------------------------------|
| 1. No. <u>A-3391-10</u> | | 4. Present Name(s) Tyree, Larry - House | | 1. No. <u>3391-10</u> | | | | | | | | | | | | | | | | | | | | |
| 2. County Franklin | | 5. Other Name(s) Pierce House | | | 2. County FRANKLIN | | | | | | | | | | | | | | | | | | | |
| 3. Location of Negatives Col. Dept. of Job Developmt. | | | | | | 4. Present Name(s) TYREE, LARRY | | | | | | | | | | | | | | | | | | |
| 6. Specific Location 177 W. Jeffrey Place | | 16. Thematic Category D | | 28. No. of Stories <u>2½</u> | | | | | | | | | | | | | | | | | | | | |
| 7. City or Town If Rural, Township & Vicinity Columbus | | 17. Date(s) or Period 1921 | | 29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> | | | | | | | | | | | | | | | | | | | | |
| 8. Site Plan with North Arrow  | | 18. Style or Design English Country House Influence | | 30. Foundation Material Brick | | | | | | | | | | | | | | | | | | | | |
| 9. U.T.M. Reference <table border="1" style="width: 100%;"><tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr><tr><td>Zone</td><td>Easting</td><td colspan="2">Northing</td><td colspan="6"> </td></tr></table> | | | | | | | | | | | | Zone | Easting | Northing | | | | | | | | 19. Architect or Engineer Unknown | | 31. Wall Construction Frame |
| | | | | | | | | | | | | | | | | | | | | | | | | |
| Zone | Easting | Northing | | | | | | | | | | | | | | | | | | | | | | |
| 10. Site Building <input checked="" type="checkbox"/> Structure <input type="checkbox"/> Object <input type="checkbox"/> | | 20. Contractor or Builder Unknown | | 32. Roof Type & Material Clipped Gable/Slate | | | | | | | | | | | | | | | | | | | | |
| 11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> | | 21. Original Use, if apparent Residence, Single Family | | 33. No. of Bays Front <u>3</u> Side <u>4</u> | | | | | | | | | | | | | | | | | | | | |
| 12. Is It Eligible? Yes <input type="checkbox"/> No <input type="checkbox"/> | | 22. Present Use Residence, Single Family | | 34. Wall Treatment Vinyl siding | | | | | | | | | | | | | | | | | | | | |
| 13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> | | 23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/> | | 35. Plan Shape Irregular | | | | | | | | | | | | | | | | | | | | |
| 14. District Potent'l? Yes <input type="checkbox"/> No <input type="checkbox"/> | | 24. Owner's Name & Address, if known Larry Tyree 177 W. Jeffrey Pl., Columbus, OH | | 36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input checked="" type="checkbox"/> Moved <input type="checkbox"/> | | | | | | | | | | | | | | | | | | | | |
| 15. Name of Established District | | 25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> | | 37. Condition Interior <u>Excellent</u> Exterior <u>Excellent</u> | | | | | | | | | | | | | | | | | | | | |
| | | 26. Local Contact Person or Organization Old Beechwold Association | | 38. Preservation Underway? Yes <input type="checkbox"/> No <input type="checkbox"/> | | | | | | | | | | | | | | | | | | | | |
| | | 27. Other Surveys in Which Included NATIONAL REGISTER | | 39. Endangered? By What? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Morse/Bethel Conn. | | | | | | | | | | | | | | | | | | | | |
| 42. Further Description of Important Features (Continue on reverse if necessary) Gable ends have bargeboard with brackets; front windows have been altered; front door has shed roofed hood supported by brackets; windows are a combination of casement and double hung sash. | | | | 40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> | | | | | | | | | | | | | | | | | | | | |
| 43. History and Significance The original owner was George W. Pierce, manager of the Remington Typewriter Co. in Columbus. | | | | 41. Distance from and Frontage on Road D. 40' - Fr. 60' | | | | | | | | | | | | | | | | | | | | |
| 44. Description of Environment and Outbuildings Frame two-car garage with large dormer and slate roof. | | | | 5. Other Name(s) Pierce House | | | | | | | | | | | | | | | | | | | | |
| 45. Sources of Information City Directories and Parcel Records | | 46. Prepared by Betty Urban | | | | | | | | | | | | | | | | | | | | | | |
| | | 47. Organization Old Beechwold Assn. | | | | | | | | | | | | | | | | | | | | | | |
| | | 48. Date 1984 | 49. Revision Date(s) | | | | | | | | | | | | | | | | | | | | | |

50. House Type No.

Code No. Name

51. Historic Outbuildings and Dependencies

Barn Type(s)

Code No. Type

Corn Crib or Shed Smoke House, Privy
Silo Spring House Carriage House
Summer Kitchen or Ice House

Other _____


52. Archaeological Site on Property?

Yes
No

Basis for Information

Owner Collection
Above Ground Earthworks or Mound
Cultural Materials Noted OAI No. _____

53. Farmstead Plan



54. Photo

Roll No. _____ Picture No(s). _____

42. (Cont'd)

NATIONAL REGISTER