





# OHIO HISTORIC INVENTORY

1. No. A-3423-10	4. Present Name(s) Lundstedt, Sven - House
2. County Franklin	5. Other Name(s) SNOW - House
3. Location of Negatives Col. Dept. of Jobs Devel.	

1. No.  
3423-10

6. Specific Location 197 Riverview Park Dr.	16. Thematic Category D	28. No. of Stories 2
7. City or Town If Rural, Township & Vicinity	17. Date(s) or Period c. 1930	29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
8. Site Plan with North Arrow 	18. Style or Design English Country	30. Foundation Material concrete
9. U.T.M. Reference Zone Easting Northing	19. Architect or Engineer	31. Wall Construction frame
10. Site <input type="checkbox"/> Building <input checked="" type="checkbox"/>	20. Contractor or Builder	32. Roof Type & Material Hip, asphalt shingle
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	21. Original Use, if apparent Residential	33. No. of Bays Front 4 Side 2
12. Is It Eligible? Yes <input type="checkbox"/> No <input type="checkbox"/>	22. Present Use Residential	34. Wall Treatment Stucco & shingles
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>	35. Plan Shape Rectangle
14. District Potent'l? Yes <input type="checkbox"/> No <input type="checkbox"/>	24. Owner's Name & Address, if known Sven Lundstedt 197 Riverview Park Dr. Columbus OH 43214	36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/>
15. Name of Established District	25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	37. Condition Interior <u>Excellent</u> Exterior <u>Excellent</u>
	26. Local Contact Person or Organization	38. Preservation Underway? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	27. Other Surveys in Which Included  <b>NATIONAL REGISTER</b>	39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
		41. Distance from and Frontage on Road

2. County  
FRANKLIN  
4. Present Name(s)  
LUNDSTEDT, SVEN

42. Further Description of Important Features (Continue on reverse if necessary) Main 2-story hip roof block has gable in front and hipped roof dormer on side. Front windows have 6/6 double hung sash, other windows have 4/4 double hung sash grouped in 2's and 3's. Coursed stone chimney in front. Stucco walls, with wood shingles on doors and gable ends.	
---	---

5. Other Name(s)  
SNOW

43. History and Significance The house was built by George Van Bolt, president of the Van Bolt Kreber Company.
---

44. Description of Environment and Outbuildings 3 car gabled garage at rear.
---

45. Sources of Information Owner City Directory parcel Records	46. Prepared by Rex Hagerling
	47. Organization
	48. Date
	49. Revision Date(s)

50. House Type No.

Code No. Name

\_\_\_\_\_

51. Historic Outbuildings and Dependencies

Barn Type(s)

Code No. Type

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Corn Crib or Shed  Silo  Summer Kitchen  Smoke House,  Spring House or Ice House Privy  Carriage House

Other \_\_\_\_\_


52. Archaeological Site on Property?

Yes   
No

Basis for Information

Owner Collection   
Above Ground Earthworks or Mound   
Cultural Materials Noted  OAI No. \_\_\_\_\_

53. Farmstead Plan



54. Photo

Roll No. \_\_\_\_\_ Picture No(s). \_\_\_\_\_

42. (Cont'd)