




## OHIO HISTORIC INVENTORY

1. No. <u>2A-3433-10</u>		4. Present Name(s) Carlisi, Thomas - House		1. No. 3433-10	
2. County Franklin		5. Other Name(s)			2. County FRANKLIN
3. Location of Negatives Col. Dept. of Jobs Devel.					
6. Specific Location 157 Rustic Place		16. Thematic Category D		28. No. of Stories 2	
7. City or Town If Rural, Township & Vicinity Columbus		17. Date(s) or Period 1940		29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
8. Site Plan with North Arrow 		18. Style or Design English Country House		30. Foundation Material Concrete block	
9. U.T.M. Reference Zone Easting Northing		19. Architect or Engineer F. Edgar Outcault		31. Wall Construction Frame & stone	
10. Site <input type="checkbox"/> Building <input checked="" type="checkbox"/>		20. Contractor or Builder		32. Roof Type & Material Gable / asbestos shingle	
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		21. Original Use, if apparent Residence		33. No. of Bays Front 3 Side 2	
12. Is It Eligible? Yes <input type="checkbox"/> No <input type="checkbox"/>		22. Present Use Residence		34. Wall Treatment Shingle/stone	
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>		35. Plan Shape Rectangle	
14. District Potent'l? Yes <input type="checkbox"/> No <input type="checkbox"/>		24. Owner's Name & Address, if known Thomas Carlisi 157 Rustic Place Columbus OH 43214		36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/>	
15. Name of Established District		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		37. Condition Interior <u>Very good</u> Exterior <u>Very good</u>	
42. Further Description of Important Features (Continue on reverse if necessary) Unpainted square shingles on 2nd floor, 1st flr stone set into concrete. Swan's neck pediment over front door. Oblong niche in front wall, small octagonal window, 2 casement windows with transoms & paneled aprons. Two large gables. One intersected by chimney. Shed dormers with elliptical roofs. Attached front garage.		26. Local Contact Person or Organization Pres., Old Beechwold Assn.		38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
43. History and Significance Built for Walter H. Wills, Central Ohio Paper Co. who lived here until 1964 when he moved to 30 W. Beechwold. 1964-81 Jan Korringa, prof. OSU. 1981-83 Dr. James C. Good.		27. Other Surveys in Which Included  <b>NATIONAL REGISTER</b>		39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
44. Description of Environment and Outbuildings No outbuildings. A number of large old trees including evergreens. Several red buds.		46. Prepared by Mildred M. Mangum		5. Other Name(s)	
45. Sources of Information Present owners. Columbus City Directories		47. Organization Old Beechwolds Assn.			
		48. Date 5/84			
		49. Revision Date(s)			

50. House Type No.

Code No. Name

\_\_\_\_\_

51. Historic Outbuildings and Dependencies

Barn Type(s)

Code No. Type

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Corn Crib or Shed  Silo  Summer Kitchen  Smoke House,  Spring House or Ice House  Privy  Carriage House

Other \_\_\_\_\_

52. Archaeological Site on Property?

Yes   
No

Basis for Information

Owner Collection   
Above Ground Earthworks or Mound   
Cultural Materials Noted  OAI No. \_\_\_\_\_

53. Farmstead Plan



54. Photo

Roll No. \_\_\_\_\_ Picture No(s). \_\_\_\_\_

42. (Cont'd)

UNIVERSITY OF MICHIGAN