

Ohio Historic Preservation Office  
Ohio Historical Center  
Columbus, Ohio 43211

1. No. 168. FRA-1866-3		4. Present Name(s) SLAUGHTER RESIDENCE	
2. County FRANKLIN		5. Other Name(s) RORER RESIDENCE	
3. Location of Negatives OHS.			
6. Specific Location 314 KANAWA AVE.		16. Thematic Category 20th cen.	
7. City or Town If Rural, Township & Vicinity COLUMBUS		17. Date(s) or Period c 1940.	
8. Site Plan with North Arrow 		18. Style or Design LOG CABIN	
9. Coordinates Lat. _____ Long. _____ U.T.M. Reference Zone _____ Easting _____ Northing _____		19. Architect or Engineer	
10. Site <input type="checkbox"/> Building <input checked="" type="checkbox"/> Structure <input type="checkbox"/> Object <input type="checkbox"/>		20. Contractor or Builder MR RORER	
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		21. Original Use, if apparent	
12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		22. Present Use HOUSE.	
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>	
14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		24. Owner's Name & Address, if known SLAUGHTER RESIDENCE 314 KANAWA COLUMBUS	
15. Name of Established District		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
42. Further Description of Important Features HOUSE IS CONSTRUCTED OF LOGS INFILLED WITH MUD OR CEMENT. THERE IS A PORCH ON THE FRONT OF THE HOUSE SUPPORTED BY LOGS. 3 CORNER WINDOWS WERE ADDED AT A LATER DATE. THERE IS A GARAGE ATTACHED TO THE EAST. HOUSE WAS BUILT FROM LOGS FROM AN OLD BARN.		26. Local Contact Person or Organization MR SLAUGHTER.	
43. History and Significance ORIGINALLY BUILT BY A MR RORER IN 1944. IT WAS OWNED BY HE AND HIS WIFE UNTIL 1959 WHEN IT WAS SOLD TO RUTH LISK. WM. SLAUGHTER BOUGHT IN IN 1973.		27. Other Surveys in Which Included	
44. Description of Environment and Outbuildings LOCATED IN N. COLUMBUS RESIDENTIAL AREA, MOST OF HOMES BUILT IN 1930'S - 1950'S		28. No. of Stories 1 1/2	
45. Sources of Information VISUAL INSPEC. FRANKLIN CO. TAX RECORDS.		29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
		30. Foundation Material STONE	
		31. Wall Construction LOG.	
		32. Roof Type & Material GABLED / SHINGLE	
		33. No. of Bays Front 3 Side 2	
		34. Wall Treatment LOGS	
		35. Plan Shape REC.	
		36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input checked="" type="checkbox"/> Moved <input type="checkbox"/>	
		37. Condition Interior GOOD Exterior GOOD	
		38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
		39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
		41. Distance from and Frontage on Road 30' x 40'	
		46. Prepared by HOBSTETTER	
		47. Organization COW. INV.	
		48. Date 8-27	
		49. Revision Date(s)	

## 51. Condition of Property

- ☐ Excellent  
☐ Good/Fair  
☐ Deteriorated

☐ Ruin☐ Destroyed/Burned

Date \_\_\_\_\_

## 52. Historic Outbuildings and Dependencies

Barn Type(s)

\_\_\_\_\_

\_\_\_\_\_

Corn Crib or Shed ☐Smoke House ☐Privy ☐Summer Kitchen ☐Spring House ☐Garage ☐Silo ☐Ice House ☐Designed landscape features ☐

## 53. Affiliated OAI Site Number(s) \_\_\_\_\_ one \_\_\_\_\_ multiple

Archaeological Feature:

Observed

Expected on Basis of  
Archival Research

Well

\_\_\_\_\_

\_\_\_\_\_

Privy

\_\_\_\_\_

\_\_\_\_\_

Cistern

\_\_\_\_\_

\_\_\_\_\_

Foundation

\_\_\_\_\_

\_\_\_\_\_

Structural Rubble

\_\_\_\_\_

\_\_\_\_\_

Formal Trash Dump

\_\_\_\_\_

\_\_\_\_\_

Other \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

## 54. Farmstead Plan

┌	.	.	.	┐
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
└	.	.	.	┘

42. (Cont'd)

43. (Cont'd)