20AUG 75

OHIO HISTORIC INVENTORY

	IIIVEITIOITI	Cojumbus, Onto 43211					
1. No. FRA - 1676 -18	4. Present Name(s)	i a	44=				
2. County	65 GAST NORTH BROADWAY	7.	TRA-				
	5. Other Name(s)						
3. Location of Negatives		and the second	1676-				
C.H.S.			0				
6. Specific Location	16. Thematic Category	28. No. of Stories 之方	30 N				
65 E, HORTH BROADWA	17. Date(s) or Period	29. Basement? Yes No 🗆	2. County				
	ca 1910 - 21020	30. Foundation Material	5				
7. City or Town If Rural, Township & Vi	cinity 18. Style or Design	STOHE 31. Wall Construction	5				
8. Site Plan with North Alrow	19. Architect or Engineer	BRICK					
	-	32. Roof Type & Material					
E. HORTH	20. Contractor or Builder	GABLE REDTILE	_				
Discoult.	21. Original Use, if apparent	33. No. of Bays Front フ Side 学 3	4.0				
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Itouse	34. Wall Treatment	Seg				
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	22. Present Use	PLAIM	sent				
र्भे हैं	40056	35. Plan Shape IRREGULAR	(1) Z				
1 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	23. Ownership Public Private W	36. Changes Addition □	l. Present Name(s) 65 モ ん				
9. Coordinates	Private 70 24. Owner's Name & Address, 5 5556	(Explain Altered ☐ in #42) Moved ☐	S				
Lat. Long.	if known	37. Condition	38				
U.T.M. Reference	JOSEPH C & RUTH E DUMLEAVY C-O CENTRAL OHIO FEDERAL SAVINGS	Interior	2				
		Exterior_ <<	SECADUA?				
Zone Easting Northing 10. Site □ Structu	25. Open to Yes ☐ Public? No 🗷	38. Preservation Yes ⊠ Underway? No □	\$				
	26. Local Contact Person or Organization	39. Endangered? Yes □					
	es □	By What?					
Register? No 🕱 Eligible?	z z z z z z z z z z z z z z z z z z z	1	y .				
13. Part of Estab. Yes ☐ 14. District Y Hist. Dist.? No 🏋 Potent'l?	es □	40. Visible from Yes					
15. Name of Established District		Public Road? No 🗅 41. Distance from and					
10. Name of Established District	1	Frontage on Road					
		# 65 X 35					
42. Further Description of Important Feature	S		O1				
PLAIN BARCEBOARDS			Other				
TIMBERFRAMING IN GABLE	ENDS	10 10 10	er				
			Name(s)				
			e(s				
43. History and Significance		<i>></i> 8 ⇒					
45. History and Significance							
		*					
44. Description of Environment and Outbuild	lings AKIAVO I A						
HAS AN GOTRGINGLY W	lings OAKLAND LOT 29. LOCATOD LUGG SGTBARK ON GITHER SUBG	ON SCREET WRICH					
	of more on Grunde sing	-					
45. Sources of Information		46. Prepared by					
BAIST'S PROPORTY ATTAS	, 1910.	C+9					
be he as	1920	47. Organization					
		48. Date 49. Revision Date(s)	17				
			- 7				

51. Condition of Property Excellent Good/Fair Deteriorated	Ruin Destroyed/B		54. Farr	nstead Plan •	•	ī
52. Historic Outbuildings and Dependencies						
Barn Type(s)						
· · · · · · · · · · · · · · · · · · ·					٠	
Corn Crib or Shed Summer Kitchen Silo	Smoke House Spring House Ice House	☐ Garage ☐	•	•		
Designed landscape features		.				
53. Affiliated OAI Site Number(s)	one.	multiple				
Archaeological Feature:	Observed	Expected on Basis of Archival Research				
Well Privy Cistern Foundation Structural Rubble						
Formal Trash Dump Other			Ŀ			<u>.</u>
42. (Cont'd)						

43. (Cont'd)