



OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

1. No. 142 FRA-1840-10		4. Present Name(s) DR. S. CORSON RESIDENCE.		FRA-1840-10	142	
2. County FRANKLIN		5. Other Name(s) J. HARVEY ZINN RES.				
3. Location of Negatives OHS						
6. Specific Location 285 KENWORTH.		16. Thematic Category D 20TH CEN ARCH.		28. No. of Stories 2 1/2	FRANKLIN	
7. City or Town If Rural, Township & Vicinity COLUMBUS.		17. Date(s) or Period C 1920		29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		
8. Site Plan with North Arrow 		18. Style or Design		30. Foundation Material STONE		
9. Coordinates Lat. _____ Long. _____ U.T.M. Reference _____		19. Architect or Engineer		31. Wall Construction WOOD.		
Zone _____ Easting _____ Northing _____		20. Contractor or Builder		32. Roof Type & Material GABLED SHINGLE.		
10. Site <input type="checkbox"/> Building <input checked="" type="checkbox"/> Structure <input type="checkbox"/> Object <input type="checkbox"/>		21. Original Use, if apparent HOUSE		33. No. of Bays Front 10. Side 2		
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		22. Present Use HOUSE.		34. Wall Treatment LAPPED SIDING		
12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>		35. Plan Shape		
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		24. Owner's Name & Address, if known DR. CORSON 285 KENWORTH COLUMBUS.		36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/>		
14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		37. Condition Interior GOOD Exterior GOOD		
15. Name of Established District		26. Local Contact Person or Organization DR. CORSON.		38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	DR. S. CORSON RES.	
42. Further Description of Important Features HOUSE IS WOOD FRAME WITH A SHINGLE ROOF. THERE ARE DORMER WINDOWS ALONG THE GARAGE ROOF AND THE MAIN HOUSE. THERE ARE 2 PORCHES WITH THE W. SIDE HAS A LARGE PORCH WHICH FACES THE RIVER. THERE ARE SEMICIRCULAR FAN PATTERNS OVER SEVERAL OF THE WINDOWS.		27. Other Surveys in Which Included		39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		
43. History and Significance PROPERTY WAS OWNED BY J. ZINN FROM 1920-1959 EMMA ZINN 1959-1962 SAMUEL CORSON 1962-				40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		
44. Description of Environment and Outbuildings LOCATED ALONG OQUANTANGY RIVER. HOUSE IS SET BACK FROM STREET AND SURROUNDED WITH LARGE TREES.				41. Distance from and Frontage on Road 60' x 100'		
45. Sources of Information VISUAL INSPECTION. FRANKLIN CO TAX RECORDS						
		46. Prepared by HOBBSTETTER				
		47. Organization COS. INVENTORY.				
		48. Date 8/24/75		49. Revision Date(s)		J. HARVEY ZINN RES.

51. Condition of Property

- ☐ Excellent
☐ Good/Fair
☐ Deteriorated

☐ Ruin☐ Destroyed/Burned

Date _____

52. Historic Outbuildings and Dependencies

Barn Type(s)

Corn Crib or Shed ☐Smoke House ☐Privy ☐Summer Kitchen ☐Spring House ☐Garage ☐Silo ☐Ice House ☐Designed landscape features ☐

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:

Observed

Expected on Basis of
Archival Research

Well

Privy

Cistern

Foundation

Structural Rubble

Formal Trash Dump

Other _____

54. Farmstead Plan

┌	.	.	.	┐
.
.
.
.
.
.
.
└	.	.	.	┘

42. (Cont'd)

43. (Cont'd)