48. Date

7/84

49. Revision Date(s)

OHIO HISTORIC INVENTORY

1985 Velma Avenue Columbus, Ohio 43211 614/466-1500

HISTORICAL SOCIETY
SINCE 1885

4. Present Name(s)

5. Other Name(s)

0111011011110							
1. No. A - 3398 - 10 2. County	4. Present Name(s) Moots, Philip δ	Patricia - house					
Franklin 3. Location of Negatives	5. Other Name(s)	ther Name(s)					
Cols. Dept. of Jobs Devel.							
6. Specific Location	16. Thematic Category	28. No. of Stories 2					
	D	29. Basement? Yes ⊠					
4783 Olentangy Blvd.	17. Date(s) or Period c. 1938	30. Foundation Material concrete					
7. City or Town If Rural, Township & \	/icinity 18. Style or Design	concrete					
Columbus	Cape Cod	31. Wall Construction					
8. Site Plan with North Arrow	19. Architect or Engineer	frame					
	W. A. Paine 20. Contractor or Builder	32. Roof Type & Material gable, wood shingles					
to the	20. Contractor of Builder	33. No. of Bays					
2 N	21. Original Use, if apparent	Front 5 Side 2					
ž/ N	Residential	34. Wall Treatment wood shingles					
9(22. Present Use	wood shingles					
Rustic A.	Residential	35. Plan Shape rectangular					
		lic 🗆 36. Changes Addition 🖾 🛱					
		ate ☑ (Explain Altered □ □					
1	24. Owner's Name & Address,						
Q III M Poterana	if known Phil Moots	37. Condition					
9. U.T.M. Reference	4783 Olentangy Blv	7d.					
	Columbus OH 43214	Exterior excellent					
Zone Easting Northing 10. Site □ Struc	Dublio?	'es □ 38. Preservation Yes ¾□ No ☑ Underway? No □					
	ture						
	Yes Pres., Old Beechwold Assn.	By What?					
Register? No 😡 Eligible?	No 27. Other Surveys in Which Included						
13. Part of Estab. Yes ☐ 14. District Hist. Dist.? No ☒ Potent'l?	Yes 🗆	40. Visible from Yes ᡯ Public Road? No □					
15. Name of Established District	NATIONAL REGISTER	41. Distance from and = 50					
To. Name of Established Blother	MALIGIANE MEGIOTEM	Frontage on Road = 70					
42. Further Description of Important Feature	res (Continue on reverse if necessary)						
basement stairwell entrance arched breezeway; porch wes decoration. Wood shingles h	adows 8/8. Shutter w/"S" hinges, exected (east end), garage (east) attached to end; central interior chimney. Mand split, dark grey. Addition: Kinge, with skylight and several windows.	ed by Minimal itchen					
43. History and Significance							
Written up in American Home	e, March 1941, p. 106. Exterior apne. Present owner is an attorney;	ppearance has been maintained Mrs. Moots is Ohio Art					
44. Description of Environment and Outbui							
Many large trees (oaks and	maples mostly). Old play house N	W corner of yard, gabled					
tongue and groove.							
45. Sources of Information		46. Prepared by					
Owner	M. Kaiser						
47. Organization							
		Old Beechwold Assn.					

50. House Type No.		53. Farmstead Plan				
Code No. Name	Γ.	•		•	٦	
51. Historic Outbuildings and Dependencies						
Barn Type(s)	•	•	•	•	•	
Code No. Type						
		•				
Corn Crib or Shed		•				
Other						
52. Archaeological Site on Property?	•	•				
Yes No						
Basis for Information	L°	•	•	•	-1	
Owner Collection Above Ground Earthworks or Mound Cultural Materials Noted OAI No	54. Ph Ro	oto II No	_ Picture No(s)		

42. (Cont'd)

MATERIAL REGISTER