1985 Velma Avenue Columbus, Ohio 43211



49. Revision Date(s)

48. Date 7/84

DHIO HISTORIC INVENTORY 614/466-1500 4. Present Name(s) 1. No. 3402-10 Munts-Rutherford, Andrew & K.S.D., House 2. County 5. Other Name(s) Franklin 3. Location of Negatives Harmon, John & Sidney, house 0 Col. Dept. of Jobs Devel. FRANKLIN 6. Specific Location 16. Thematic Category 28. No. of Stories 71/2 County 29. Basement? Yes 🖾 No 🗆 17. Date(s) or Period 4827 Olentangy Blvd. 1927 30. Foundation Material 7. City or Town If Rural, Township & Vicinity 18. Style or Design Columbus Bungalow-type 31. Wall Construction frame 8. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material Gable, shingle 20. Contractor or Builder 33. No. of Bays MUNTS-RUTHERFORD Side 1 Front 3 21. Original Use, if apparent Present Name(s) Residential 34. Wall Treatment 22. Present Use Stucco Residential 35. Plan Shape Rectangular 23. Ownership Public 36. Changes Addition & Private 13 (Explain Altered in #42) Moved □ 24. Owner's Name & Address. if known Andrew D. & K.S. Munts-37. Condition Fair 9. U.T.M. Reference Interior 4827 Olentangy Rutherford Exterior Fair (being improved Columbus OH 43214 Andrew Easting 25. Open to Zone Northing Yes 38. Preservation Public? No 🖾 Underway? 10. No 🗆 Site Structure Building X Object 39. Endangered? 26. Local Contact Person or Organization Yes By What? No 🗆 11. On National Yes 12. Is It Yes Pres., Old Beechwold Assn. 8 Register? Eligible? к. No 🔯 No 🗆 27. Other Surveys in Which Included 13. Part of Estab. Yes 14. District Yes 40. Visible from Yes X S Potent'l? Hist. Dist.? No 😾 No \Box Public Road? No 🗆 NATIONAL REGISTER b 15. Name of Established District 41. Distance from and Frontage on Road Approx. 65'; 40' 42. Further Description of Important Features (Continue on reverse if necessary) Arched entry. Chimney, front, stepped. Gabled ends with louvers. Other Name(s Wood shingled addition on north side, 2nd flr. Separate garage (stucco & wood shingle, gabled). Stone terraced front entry. Chimney has random stone projections. Larger window south end of many small panes. 43. History and Significance HARMON, Built as honeymoon cottage, added on later for upstairs bedroom and bath. 44. Description of Environment and Outbuildings Treed lot. House sits on bank of Olentangy River and city park ravine. Beautiful landscaping in back plus large trees. 45. Sources of Information 46. Prepared by Realtor & visual. M. Kaiser 47. Organization Old Beechwold Assn.

50. House Type No.		53. Farmstead Plan				
Code No. Name	г.	•	•		7	
51. Historic Outbuildings and Dependencies						
Barn Type(s)	•	•	•	•	•	
Code No. Type						
			•	•		
	100					
Corn Crib or Shed ☐ Smoke House, ☐ Privy ☐ Silo ☐ Spring House ☐ Carriage House ☐ Summer Kitchen ☐ or Ice House						
Other						
52. Archaeological Site on Property?			•	1.0	•	
Yes □ No □						
Basis for Information	Ŀ	•	•	• ,,,,	. 7	
Owner Collection Above Ground Earthworks or Mound Cultural Materials Noted OAI No	54. P	hoto oll No.	Picture No(s)		

42. (Cont'd)

HITETORY INC. INC.